NYC 9/11 Public Portal Document

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0620

WARREN & PANZER ENGINEERS, P. C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

(24 hr+/a) [circled] 12 hr+/a 6 hr+/a 3 hr+/a Immediate +/a

P.O. ______

CLIENT: D.E.P.
PROJECT: DEP Sampling: Roof Cleaning
LOCATION: 24 John St. NY. NY. on Roof.

W&P FILE #: 1079.01.02
LABORATORY: Warren and Panzer.
ANALYSIS METHOD: circle one PCM 7400 / TEM AHERA [circled] / TEM EPA LEVEL II
TECHNICIAN: Yury Bedin.

CONTACT: Mr. M. Nalan.

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (fib./cc.)
1 IWA	on Roof, 4th Fl. Center of Work Area.	3		3.0	3.0	9:15	16:45	450	1350	
2 IWA	on Roof 4th Fl. West Section of W.A.	3		3.0	3.0	9:17	16:47	450	1350	
3 IWA	on Roof 4th Fl. North Section of W.A.	3		3.0	3.0	9:19	16:49	450	1350	
4 IWA	on Roof 4th Fl. East Section of W.A.	3		3.0	3.0	9:21	16:51	450	1350	
5 OWA	4th Fl. on Hallway (Exit Door Entrance) Leading to Roof.	3		3.0	3.0	9:23	16:53	450	1350	
6 —	Field Blank —	1	—	—	—	—	—	—	—	
7 —	Field Blank —	1	—	—	—	—	—	—	—	
8 —	S. Blank —	1	—	—	—	—	—	—	—	

COMMENTS:

T02-10-048

SAMPLE BY: Yury Bedin. DATE: 10-7-02.
SIGNATURE: [signature]
RELEASED BY: Yury Bedin. DATE: 10-7-02
SIGNATURE: [signature] Released 18:31 PM.
RECEIVED BY: A. Cajigal DATE: 10/8/02
SIGNATURE: A. CAJIGAL

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION