

Asbestos Inspection Report

Premise No. 24 JOHN STREET					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 65	Lot 24	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
WEDNESDAY OCTOBER 2 2002 (0800AM - 0800PM) THE CLEAN UP OF THE ROOF (HIGH) AND THE ADJACENT FIRE ESCAPE WAS BEGUN. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY DIPO ELEMO (CERTIFICATE # AH 01-14694 EXP 03/03)						
THURSDAY OCTOBER 3 2002 TO FRIDAY OCTOBER 4, 2002 (0800AM - 0800PM) THE CLEAN UP OF THE ROOF WORK AREAS AND THE FIRE ESCAPE IS COMPLETED. AIR SAMPLING IS PERFORMED BY DIPO ELEMO.						
SATURDAY OCTOBER 5 2002 (0600AM - 0600PM) THE CLEAN UP OF THE NORTH FACADE OF THE PREMISE WAS CONDUCTED. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT RUN OFF WATER. A DECONTAMINATION TRUCK WAS UTILIZED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CHETRAM RAMRAJ (CERTIFICATE # AH 98-19842 EXP 01/03). AIR SAMPLES WERE RUN ON THE OPPOSITE SIDEWALK. THE CLEAN UP OF THE NORTH FACADE OF 22 JOHN STREET OCCURRED SIMULTANEOUSLY. FOR THE PURPOSES OF AIR MONITORING, THE FACADE OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. UPON COMPLETION OF THE CLEAN UP ACTIVITIES, CHETRAM RAMRAJ CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP OF THE SOUTH FACADE AND SET BACK AREA BEGAN. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY JESRON GARCIA (CERTIFICATE # AH 01-11633 EXP 03/03).						
MONDAY OCTOBER 7 2002 THE CLEAN UP OF THE SOUTH FACADE CONTINUES. THE CLEAN UP OF THE PIT AREA NEAR THE FIRE ESCAPE BEGINS.						