

228 East 45th Street
New York, NY 10017
(212) 922-0877
Fax (212) 922-0820

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

P.O. _____

CLIENT: D.E.P.

W&P FILE #: 1079.01.02

LABORATORY: Warren and Panzer

CONTACT: Mr. M. Nalan

PROJECT: DEP Sampling: Roof Cleaning

LOCATION: 24 John St. NY, NY.

ANALYSIS METHOD: PCM TEM TEM
circle one 7400 AHERA EPA LEVEL II

TECHNICIAN: Vury Bedin

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE		TIME		TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
				START	STOP	ON	OFF			
1 IWA	on Roof 4 th Fl. Center of North Area	3		3.0	3.0	9:15	16:45	450	1350	
2 IWA	on Roof 4 th Fl. West Section of W.A.	3		3.0	3.0	9:17	16:47	450	1350	
3 IWA	on Roof 4 th Fl. North Section of W.A.	3		3.0	3.0	9:19	16:49	450	1350	
4 IWA	on Roof 4 th Fl. East Section of W.A.	3		3.0	3.0	9:21	16:51	450	1350	
5 OWA	4 th Fl. on Hallway leading to Roof	3		3.0	3.0	9:23	16:53	450	1350	
6 —	Field Blank	1								
7 —	Field Blank	1								
8 —	S. Blank	1								

COMMENTS:

SAMPLE BY: Vury Bedin DATE: 10-7-02
SIGNATURE: Vury Bedin
RELEASED BY: Vury Bedin DATE: 10-7-02
SIGNATURE: Vury Bedin Released 18:31 PM.
RECEIVED BY: A. CAJIGAL DATE: 10/8/02
SIGNATURE: A. CAJIGAL

T02-10-048

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

10/10/2002 08:50 FAX

014/015