

WTC Visual Survey Form

1001105

Premise Address: <u>242 John St</u>		
Block: <u>65</u>	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
Lot: <u>24</u>		
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc. Facades and windows are still dirty</u>					
Roof					
<i>Light dust</i>					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>NO ACCESS into bldg</u>					

Date: 3/2/2002

Inspection Team: Name: AL

Agency: _____
Agency: _____