

WTC Visual Survey Form

1002071

✓

Premise Address: 20 Harrison St

Block: 1-81 Residential ☒ Commercial ☐ Name of Building: LANDMARK
 Lot: 6 Mix Use ☐ Other ☐

of Stories: 6 AKA's:

Building Owner/Management: Telephone Number: ()
 Name: Leonard-Gunilla Vickers FAX: ()

Address: 20 Harrison St, New York, NY 10013-2810

On Site Contact: Telephone Number: ()
 Name:

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No Locations: _____
 ACM Clean Up ☐ Yes ☐ No Locations: _____
 Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

North ☐ N/A
 South ☐ N/A
 East ☐ N/A
 West ☐ N/A

Inspected

☐ Yes ☐ No
☒ Yes ☐ No
☐ Yes ☐ No
☐ Yes ☐ No

Debris

☐ No Visible/Fine Layer
☒ No Visible/Fine Layer
☐ No Visible/Fine Layer
☐ No Visible/Fine Layer

☐ ½ to 1" ☐ > 1"
☐ ½ to 1" ☐ > 1"
☐ ½ to 1" ☐ > 1"
☐ ½ to 1" ☐ > 1"

Facade Description:

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
 Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/11/2002

ENTERED

Inspection Team: Name:

Name:

Agency:

Agency: