

WTC Visual Survey Form

1002082

✓

Premise Address: 24 Harmon St

Block: 81 Residential ☐ Commercial ☐ Name of Building: LANDMARK

Lot: 4 Mix Use ☐ Other ☐

of Stories: 24-26 AKA's: HARRISON ST.

Building Owner/Management: Gael Milner Telephone Number: ()

Name: Gael Milner FAX: ()

Address: B W Goepf St Bethlehem PA 18018-2706

On Site Contact: Gael Milner Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/11/2002Inspection Team: Name: CHACAgency: _____
Agency: _____