

<u>AAA</u>		
142/10	187 Harrison	
142/11	27	
142/12	315	
142/13	29	
142/14	31	
142/16	33	
142/17	37	
142/18	39	
142/19	41	

OKAY.

142/25

WTC Visual Survey Form

1083157

Premise Address: 310 Greenwich St Complex 1083157

Block: 142 Residential ☒ Commercial ☒ Name of Building: _____
 Lot: 25 Mix Use ☒ Other ☒

of Stories: _____ AKA's: 308-310 GREENWICH ST / 352-354 GREENWICH ST / 34-40 HARRISON ST.

Building Owner/Management: _____ Telephone Number: () 364-376 GREENWICH STREET
 Name: DUANE STREET ASSOC. 40 HUDSON RIVER MGMT. FAX: () _____

Address: P.O. BOX 1763, N.Y. N.Y. 10156-1763

On Site Contact: _____ Telephone Number: () _____
 Name: Louis Baptista

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No Locations: _____
 ACM Clean Up ☐ Yes ☐ No Locations: _____
 Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks ☐ N/A

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/11/2002Inspection Team: Name: CARL

Agency: _____

Name: _____

Agency: _____

ENTERED