

ENVIROSCIENCE CONSULTANTS, INC.

2150 SMITHTOWN AVENUE
RONKONKOMA, NEW YORK 11779
PHONE: (631) 580-3191
FACSIMILE: (631) 580-3195
WWW.ENVIROHEALTH.ORG

PCM AIR SAMPLE RESULTS

CLIENT:	American Stock Exchange	SAMPLE DATE:	February 23, 2002
PROJECT NAME:	86 Trinity Place New York, NY	SAMPLE TYPE:	During Abatement
AREA:	Roof Debris Cleaning	SAMPLER:	G. Gabay
CLIENT #:	01-10445	CUSTODY #:	B-28-23

Sample #	Sample Location	Start	End	Run Time	Start F/R	End F/R	Volume	Fibers	Fields	Fibers/cc
D1	Top of stairs by door to 10th floor roof	9:15	11:30	75	10	10	750	0	100	0.0065
D2	Inside the door to 10th floor roof stair	9:15	11:30	75	10	10	750	2	100	0.0065
D3	Outside bank A elevators 10th floor	9:15	11:30	75	10	10	750	1	100	0.0065
D4	Outside women's bathroom 10th floor	9:16	11:31	75	10	10	750	6	100	0.0065
D5	Outside Room 1004	9:16	11:31	75	10	10	750	2	100	0.0065
D6	Top of stairs by door to 15th floor roof	10:02	13:05	183	10	10	1830	2	100	0.0027
D7	Bottom of stairs on 15th floor	10:02	13:05	183	10	10	1830	8	100	0.0027
D8	Outside bank A elevators 15th floor	10:02	13:05	183	10	10	1830	5	100	0.0027
D9	By doors to offices, 15th floor	10:03	13:06	183	10	10	1830	2	100	0.0027
D10	By doors to offices, 15th floor	10:03	13:06	183	10	10	1830	6	100	0.0027
D11	Blank						0	0	100	0.0000
D12	Blank						0	0	100	0.0000

Method: NIOSH 7400 - Phase Contrast Microscopy

NYS ELAP No.: 11681

F/R = Flow Rate F = Fibers

Date Issued: 2.27.02

Reviewed by: 

Laboratory Manager