

ENVIROSCIENCE CONSULTANTS, INC.

2150 SMITHTOWN AVENUE
RONKONKOMA, NEW YORK 11779
PHONE: (631) 580-3191
FACSIMILE: (631) 580-3195
WWW.ENVIROHEALTH.ORG

PCM AIR SAMPLE RESULTS

CLIENT:	American Stock Exchange	SAMPLE DATE:	February 23, 2002
PROJECT NAME:	86 Trinity Place New York, NY	SAMPLE TYPE:	Final Clearance
AREA:	Roof Debris Cleaning	SAMPLER:	G. Gabay
CLIENT #:	01-10445	CUSTODY #:	B-28-22

Sample #	Sample Location	Start	End	Run Time	Start F/R	End F/R	Volume	Fibers	Fields	Fibers/cc
F1	Top of stairs by door to 10th floor roof	15:05	17:40	155	12	12	1860	3	100	0.0026
F2	Inside the door to 10th floor roof stair	15:05	17:40	155	12	12	1860	7	100	0.0026
F3	Outside bank A elevators 10th floor	15:05	17:40	155	12	12	1860	3	100	0.0026
F4	Outside women's bathroom 10th floor	15:06	17:41	155	12	12	1860	2	100	0.0026
F5	Outside Room 1004	15:06	17:41	155	12	12	1860	3	100	0.0026
F6	Top of stairs by door to 15th floor roof	15:10	17:45	155	12	12	1860	1	100	0.0026
F7	Bottom of stairs on 15th floor	15:10	17:45	155	12	12	1860	2	100	0.0026
F8	Outside bank A elevators 15th floor	15:10	17:45	155	12	12	1860	2	100	0.0026
F9	By doors to offices, 15th floor	15:11	17:46	155	12	12	1860	1.5	100	0.0026
F10	By doors to offices, 15th floor	15:11	17:46	155	12	12	1860	0	100	0.0026
F11	Blank						0	0	100	0.0000
F12	Blank						0	0	100	0.0000

Method: NIOSH 7400 - Phase Contrast Microscopy

NYS ELAP No.: 11681

F/R = Flow Rate F = Fibers

Reviewed by: Edwin M. Saito Date Issued: 2-25-02

Laboratory Manager