

91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO INC. PHASE: AMBIENT DATE: 09/21/01

PROJECT ADDRESS: 67 WALL STREET, MANHATTAN, NEW YORK PROJECT LOCATION: 11TH FLOOR

TECHNICIAN: VICTOR BAJOMO JOB #: 01 - 85

[illegible]

ANALYZED BY:		DATE	TIME
APPROVED BY:		9/25/01	

**91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300**

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO INC. PHASE: AMBIENT DATE: 09/21/01

PROJECT ADDRESS:	67 WALL STREET, MANHATTAN, NEW YORK	PROJECT LOCATION:	25 TH FLOOR
			

TECHNICIAN: VICTOR BAJOMO JOB #: 01 - 85

[illegible]

DATE		TIME
ANALYZED BY:		
APPROVED BY:		9/25/01

**91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300**

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO INC. PHASE: AMBIENT DATE: 09/21/01

PROJECT ADDRESS: 67 WALL STREET, MANHATTAN, NEW YORK PROJECT LOCATION: 21ST FLOOR

TECHNICIAN: VICTOR BAJOMO JOB #: 01 - 85

[illegible]

DATE		TIME
ANALYZED BY:		
APPROVED BY:		

91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO INC. PHASE: AMBIENT DATE: 09/21/01

PROJECT ADDRESS: 67 WALL STREET, MANHATTAN, NEW YORK PROJECT LOCATION: 15TH FLOOR

TECHNICIAN: VICTOR BAJOMO

[illegible]

ANALYZED BY:		DATE	TIME
APPROVED BY:		01/25/01	

CENTRAL ENVIRONMENTAL INC.

91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT _____
 SCHLANG BROS & CO INC.
 PHASE: _____
 AMBIENT _____
 DATE: 09/22/01

PROJECT ADDRESS: 67 WALL STREET, MANHATTAN, NEW YORK PROJECT LOCATION: 19TH FLOOR

TECHNICIAN: VICTOR BAJOMO JOB #: 01 - 85

Samp. #	Sample Location						Flow In	Flow Out	Time On	Time Off	Total	Total vol.	Fiber Count	Fiber/cc	
01	IWA	19 TH FLOOR HALLWAY						5	5	0852	1103	131	655	3	<.002
02	IWA	19 TH FLOOR HALLWAY						5	5	1103	1313	130	650	5	<.004
03	IWA	19 TH FLOOR HALLWAY						5	5	1313	1524	131	655	2	<.001
04		F.B.						-	-	-	-	-	-	0	0.000
05		F.B.						-	-	-	-	-	-	0	0.000

ANALYZED BY:	DATE	TIME
APPROVED BY:	9/25/06	

91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO INC. PHASE: AMBIENT DATE: 09/22/01

PROJECT ADDRESS: 67 WALL STREET, MANHATTAN, NEW YORK PROJECT LOCATION: 13TH FLOOR

TECHNICIAN: VICTOR BAJOMO JOB #: 01 -85

[illegible]

ANALYZED BY:	DATE	TIME
APPROVED BY:	01/25/21	

**91 McClellan Street, Bronx, NY 10452
Tel: (718) 293-8727; Fax: (718) 992-4300**

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO INC. PHASE: AMBIENT DATE: 09/22/01

PROJECT ADDRESS: 67 WALL STREET, MANHATTAN, NEW YORK PROJECT LOCATION: 17TH FLOOR

TECHNICIAN: VICTOR BAJOMO
JOB #: 01 - 85

[illegible]

ANALYZED BY:	DATE	TIME
APPROVED BY:		5/5/0