

12/21/2001 17:14 FAX 2129444618

AMBIENT GROUP

004

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Ambient Group, Inc.
55 West 38th Street
New York, NY 10018

Field ID	Date Collected	Floor/Location	Concentrations Reported in ug/m ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PARK- 24	12/20/01	Loading Dock Opposite Guard Booth	0.60	1.20	10.90	113.00	9.80	5.30	1.20	37.7
75PARK- 29	12/20/01	Loading Dock Entrance To Street	0.60	1.70	13.40	693.00	2.70	9.80	1.10	51.4
75PARK- 30	12/20/01	Parking Garage Upper Level	0.80	5.90	31.60	973.00	14.60	27.80	2.90	202
75PARK- 31	12/20/01	Parking Garage Upper Level	0.50	3.20	10.10	330.00	3.60	8.60	1.70	60.4
75PARK- 32	12/20/01	Parking Garage Lower Level - South	0.50	3.20	23.30	618.00	6.30	25.00	1.70	187
75PARK- 33	12/20/01	Parking Garage Lower Level - North	0.50	3.20	10.30	390.00	1.80	9.10	1.10	55.30

12/21/2001 17:14 FAX 2129444618

AMBIENT GROUP

005

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10885

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/20/01	1058-01	Loading Dock Adjacent to Booth	0.05	0.57	0.39	5.42	0.44	0.08	0.13	0.47
12/20/01	1058-02	Loading Dock at Entrance to Street	0.08	0.49	0.44	4.45	0.44	0.08	0.13	1.07
12/20/01	1058-03	Parking Garage Near Back Exit Upper Level	0.05	0.78	0.39	1.12	0.44	0.08	0.13	0.47
12/20/01	1058-04	Parking Garage Adjacent to Soda Machine Upper Level	0.08	0.57	0.34	1.80	0.44	0.08	0.13	0.47
12/20/01	1058-05	Parking Garage Southend Lower Level	0.08	0.36	0.57	1.22	0.44	0.08	0.18	0.47
12/20/01	1059-06	Parking Garage Northend Lower Level	0.05	0.42	0.44	1.51	0.44	0.08	0.13	0.47

12/21/2001 17:14 FAX 2129444618

AMBIENT GROUP

006

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211658

Field ID Number	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/c
1056-01	12/20/01	10:12 AM	Loading Dock Adjacent to Booth	LT ANYL SENS	< 0.0045
1056-02	12/20/01	10:15 AM	Loading Dock at Entrance to Street	LT ANYL SENS	< 0.0045
1056-03	12/20/01	10:28 AM	Parking Garage Near Back Exit Upper Level	LT ANYL SENS	< 0.0045
1056-04	12/20/01	10:30 AM	Parking Garage Adjacent to Soda Machine Upper Level	LT ANYL SENS	< 0.0045
1056-05	12/20/01	10:35 AM	Parking Garage Southend Lower Level	LT ANYL SENS	< 0.0045
1057-06	12/20/01	10:37 AM	Parking Garage Northend Lower Level	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY