

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METALS IN AIR LABORATORY DATA REPORT

PROJECT ID: 211658
CLIENT: Jack Resnick & Sons
PROJECT ADDRESS: 75 Park Place
DESCRIPTION: Lobby by Elevator
COLLECTED: 11/30/01
DATE REC'D: 12/1/01
ANALYZED: 12/1/01

LABORATORY ID	FIELD ID	ANALYTE	VOLUME (L)	ug/m ³
40901	75P-MTL-1	CADMIUM	960	<0.10
		CHROMIUM	960	0.42
		COPPER	960	1.56
		IRON	960	3.80
		LEAD	960	<0.89
		MANGANESE	960	<0.16
		NICKEL	960	<0.26
		SILICA	960	1.46
		ZINC	960	<0.94

Standard/Guideline:

OSHA PEL for Cadmium: 5ug/m³; OSHA PEL for Chromium: 1000ug/m³; OSHA PEL for Copper: 1000ug/m³; OSHA PEL for Iron: 10000ug/m³; OSHA PEL for Lead: 50ug/m³; OSHA PEL for Manganese: 1000ug/m³; OSHA PEL for Nickel: 1000ug/m³; OSHA PEL for Zinc: 5000ug/m³

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10885

METALS IN AIR LABORATORY DATA REPORT

PROJECT ID: 211658

CLIENT: Jack Resnick & Sons

PROJECT ADDRESS: 75 Park Place

DESCRIPTION: Lobby by Bathroom

COLLECTED: 11/30/01

DATE REC'D: 12/1/01

ANALYZED: 12/1/01

LABORATORY ID	FIELD ID	ANALYTE	VOLUME (L)	ug/m ³
40902	75P-MTL-2	CADMIUM	960	<0.10
		CHROMIUM	960	0.57
		COPPER	960	1.82
		IRON	960	1.93
		LEAD	960	<0.89
		MANGANESE	960	<0.16
		NICKEL	960	<0.26
		SILICA	960	<1.09
		ZINC	960	<0.94

Standard/Guideline:

OSHA PEL for Cadmium: 5ug/m3; OSHA PEL for Chromium: 1000ug/m3; OSHA PEL for Copper: 1000ug/m3; OSHA PEL for Iron: 10000ug/m3; OSHA PEL for Lead: 50ug/m3; OSHA PEL for Manganese: 1000ug/m3; OSHA PEL for Nickel: 1000ug/m3; OSHA PEL for Zinc: 5000ug/m3

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METALS IN AIR LABORATORY DATA REPORT

PROJECT ID: 211658
CLIENT: Jack Resnick & Sons
PROJECT ADDRESS: 75 Park Place
DESCRIPTION: Lobby by Concierge Desk
COLLECTED: 11/30/01
DATE REC'D: 12/1/01
ANALYZED: 12/1/01

LABORATORY ID	FIELD ID	ANALYTE	VOLUME (L)	ug/m ³
40803	75P-MTL-3	CADMIUM	960	<0.10
		CHROMIUM	960	0.36
		COPPER	960	1.35
		IRON	960	3.59
		LEAD	960	<0.89
		MANGANESE	960	<0.16
		NICKEL	960	<0.26
		SILICA	960	1.46
		ZINC	960	<0.94

Standard/Guideline:

OSHA PEL for Cadmium: 5ug/m³; OSHA PEL for Chromium: 1000ug/m³; OSHA PEL for Copper: 1000ug/m³; OSHA PEL for Iron: 10000ug/m³; OSHA PEL for Lead: 50ug/m³; OSHA PEL for Manganese: 1000ug/m³; OSHA PEL for Nickel: 1000ug/m³; OSHA PEL for Zinc: 5000ug/m³

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METALS IN AIR LABORATORY DATA REPORT

PROJECT ID: 211658
CLIENT: Jack Resnick & Sons
PROJECT ADDRESS: 75 Park Place
DESCRIPTION: 10th Floor Roof Setback Facing North

COLLECTED: 11/30/01
DATE REC'D: 12/1/01
ANALYZED: 12/1/01

LABORATORY ID	FIELD ID	ANALYTE	VOLUME (L)	ug/m ³
40904	75P-MTL-4	CADMIUM	960	<0.10
		CHROMIUM	960	0.52
		COPPER	960	1.09
		IRON	960	4.17
		LEAD	960	<0.89
		MANGANESE	960	<0.16
		NICKEL	960	<0.26
		SILICA	960	1.20
		ZINC	960	<0.94

Standard/Guideline:

OSHA PEL for Cadmium: 5ug/m³; OSHA PEL for Chromium: 1000ug/m³; OSHA PEL for Copper: 1000ug/m³; OSHA PEL for Iron: 10000ug/m³; OSHA PEL for Lead: 50ug/m³; OSHA PEL for Manganese: 1000ug/m³; OSHA PEL for Nickel: 1000ug/m³; OSHA PEL for Zinc: 5000ug/m³

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METALS IN AIR LABORATORY DATA REPORT

PROJECT ID: 211658
CLIENT: Jack Resnick & Sons
PROJECT ADDRESS: 75 Park Place
DESCRIPTION: 10th Floor Roof Setback Facing East

COLLECTED: 11/30/01
DATE REC'D: 12/1/01
ANALYZED: 12/1/01

LABORATORY ID	FIELD ID	ANALYTE	VOLUME (L)	ug/m ³
40805	75P-MTL-S	CADMIUM	960	<0.10
		CHROMIUM	960	0.57
		COPPER	960	1.09
		IRON	960	6.20
		LEAD	960	<0.89
		MANGANESE	960	<0.16
		NICKEL	960	<0.28
		SILICA	960	1.88
		ZINC	960	<0.94

Standard/Guideline:

OSHA PEL for Cadmium: 5ug/m3; OSHA PEL for Chromium: 1000ug/m3; OSHA PEL for Copper: 1000ug/m3; OSHA PEL for Iron: 10000ug/m3; OSHA PEL for Lead: 50ug/m3; OSHA PEL for Manganese: 1000ug/m3; OSHA PEL for Nickel: 1000ug/m3; OSHA PEL for Zinc: 5000ug/m3

PROJECT ID: 211658
CLIENT: Jack Resnick & Sons
PROJECT ADDRESS: 75 Park Place
DESCRIPTION:

COLLECTED: 11/30/01
DATE REC'D: 12/1/01
ANALYZED: 12/1/01

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10885

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/10/01	4058-01	11th Floor: Southside	0.12	0.95	0.60	0.54	1.01	0.18	0.30	1.07
12/10/01	4058-02	11th Floor: Northside	0.12	0.89	0.60	0.30	1.01	0.18	0.30	1.07
12/10/01	4058-03	11th Floor: Central Area	0.12	0.85	0.60	0.66	1.01	0.18	0.30	1.07
12/10/01	4058-04	11th Floor: Eastside	0.12	0.60	0.60	1.07	1.01	0.18	0.30	1.07
12/10/01	4058-05	11th Floor: Westside	0.12	0.71	0.80	0.48	1.01	0.18	0.30	1.07
12/10/01	4059-01	11th Floor: Elevator Lobby	0.12	1.01	0.80	0.48	1.01	0.18	0.30	1.07
12/10/01	4059-02	11th Floor: Southwest Section	0.12	0.71	0.80	0.30	1.01	0.18	0.30	1.07
12/10/01	4059-03	10th Floor: Central Area	0.12	0.18	0.60	0.54	1.01	0.18	0.30	1.07
12/10/01	4059-04	10th Floor: Westend	0.12	0.85	0.60	0.54	1.01	0.18	0.30	1.07
12/10/01	4059-05	10th Floor: Central Area	0.12	0.60	0.60	0.48	1.01	0.18	0.30	1.07
12/10/01	4060-01	10th Floor: Southeast Corner	0.12	0.95	0.60	0.36	1.01	0.18	0.30	1.07
12/10/01	4060-02	10th Floor: Northeast Corner	0.12	0.71	0.80	0.30	1.01	0.18	0.30	1.07
12/10/01	4060-03	10th Floor: Southwest Corner	0.12	0.71	0.80	0.30	1.01	0.18	0.30	1.07
12/10/01	4060-04	10th Floor: Northwest Corner	0.12	0.48	0.60	0.30	1.01	0.18	0.30	1.07
12/10/01	4062-01	Roof: Eastside	0.12	0.71	0.60	0.20	1.01	0.18	0.30	1.07
12/10/01	4062-02	Roof: Northeast Corner	0.12	0.77	0.60	0.48	1.01	0.18	0.30	1.07
12/10/01	4062-03	Roof: Eastside	0.12	0.89	0.60	0.30	1.01	0.18	0.30	1.07
12/10/01	4062-04	Roof: Northeast Corner	0.12	0.48	0.60	0.30	1.01	0.18	0.30	1.07

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In $\mu\text{g}/\text{m}^3$							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/06/01	4074-01	14th Floor: Reception Area	0.13	1.13	1.44	4.00	1.06	0.19	0.31	1.13
12/06/01	4074-02	14th Floor: North Opposite Middle Window	0.13	0.94	1.38	0.44	1.06	0.19	0.31	1.13
12/06/01	4074-03	14th Floor: West End Adj. to Window	0.13	1.19	1.50	1.63	1.06	0.19	0.31	1.13
12/06/01	4074-04	12th Floor: N.W. Corner Large Office Area	0.14	1.27	0.99	2.75	1.20	0.21	0.35	1.27
12/06/01	4074-05	12th Floor: North Side Large Office Area	0.14	0.78	1.55	1.69	1.20	0.21	0.35	1.27
12/06/01	4075-06	12th Floor: Large Office Space	0.14	0.64	1.42	3.61	1.20	0.21	0.35	1.27
12/06/01	4075-07	12th Floor: East Office Suite	0.14	1.21	0.71	1.28	1.21	0.21	0.36	1.28
12/06/01	4075-08	12th Floor: West Office Suite	0.14	0.78	2.42	5.20	1.21	0.21	0.36	1.28
12/06/01	4075-10	Roof: North Side	0.14	0.93	1.14	3.57	1.21	0.21	0.36	1.29
12/06/01	4075-09	Roof: North West Corner	0.14	0.57	1.14	1.64	1.21	0.21	0.36	1.29

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In $\mu\text{g}/\text{m}^3$							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/7/01	4086-01	5th Floor: City Council Reception Area	0.13	0.64	1.03	0.32	1.09 *	0.19 *	0.32	1.15
12/07/01	4086-02	5th Floor: South Side Muffex Cor.	0.13	1.35	1.41 *	0.38	1.09 *	0.19 *	0.32	1.15
12/07/01	4086-03	5th Floor: City Council Storage Room	0.13	0.77	0.96	0.38	1.09 *	0.19	0.38	1.15
12/07/01	4086-04	5th Floor: Opposite R. Weinberg Office	0.13	1.35 *	0.83	0.38	1.09 *	0.19 *	0.32	1.15
12/07/01	4086-05	5th Floor: City Council South East Corner	0.13	1.22 *	1.15	0.32	1.09 *	0.19	0.32	1.15
12/7/01	4077-06	5th Floor: Opposite Computer Room	0.13	1.15 *	0.77	0.32	1.09 *	0.19	0.32	1.15
12/7/01	4077-07	5th Floor: N.W. Cor. Opposite Window	0.19 *	1.28 *	1.86 *	0.32	1.09 *	0.19	0.51	1.15
12/7/01	4077-08	Roof: Exterior N.W.	0.12	1.13	1.37	0.48	1.01	0.18 *	0.30	1.07
12/7/01	4077-09	Roof: Exterior North	0.12	1.07	0.83	0.77	1.01	0.18	0.30	1.07

01/07/2002 16:03 FAX 2129444618

AMBIENT GROUP

010/023

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Reanick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/11/01	4093-01	7th Floor: Reception Area	0.12	0.71	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4093-02	7th Floor: Opposite Stairwell Exit "X"	0.12	0.83	0.60	0.30	10.12	0.18	0.30	1.07
12/11/01	4093-03	7th Floor: Northside	0.12	0.42	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4093-04	7th Floor: Southside Near Copy Machines	0.12	0.12	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4093-05	7th Floor: Near Pantry	0.12	0.12	0.60	0.30	1.01	0.18	0.30	1.07

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported in ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/11/01	4096-06	7th Floor: Southeast Opposite Computer Room	0.12	0.24	0.89	0.30	1.01	0.18	0.30	1.07
12/11/01	4096-07	7th Floor: Northeast Section	0.12	0.65	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4096-08	8th Floor: Reception Area	0.12	0.19	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4096-09	8th Floor: Opposite Stairwell Exit "X"	0.12	0.18	0.60	0.48	1.01	0.18	0.30	1.07
12/11/01	4096-10	8th Floor: Southeast/Adjacent To Computer Room	0.12	0.18	0.60	0.89	1.01	0.18	0.30	1.07

01/07/2002 16:03 FAX 2129444618

AMBIENT GROUP

012/023

AMBIENT LABS. INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/11/01	4097-11	8th Floor: Southwest Corner	0.12	0.12	0.60	0.36	1.01	0.18	0.30	1.07
12/11/01	4097-12	8th Floor: Northeast Corner	0.12	0.12	0.60	0.71	1.01	0.18	0.30	1.07
12/11/01	4097-13	8th Floor: Central Area	0.12	0.18	0.60	0.60	1.01	0.18	0.30	1.07
12/11/01	4097-14	8th Floor: Northeast Opposite Windows	0.12	0.12	0.60	0.77	1.01	0.18	0.30	1.07
12/11/01	4097-15	Roof: East End	0.12	0.53	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4097-16	Roof: South East	0.12	0.42	0.60	0.95	1.01	0.18	0.30	1.07

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10863

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211655

Date Collected	Field ID	Description	Concentrations Reported In $\mu\text{g}/\text{m}^3$							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/11/01	4097-11	8th Floor: Southwest Corner	0.12	0.12	0.60	0.36	1.01	0.18	0.30	1.07
12/11/01	4097-12	8th Floor: Northeast Corner	0.12	0.12	0.60	0.71	1.01	0.18	0.30	1.07
12/11/01	4097-13	8th Floor: Central Area	0.12	0.18	0.60	0.60	1.01	0.18	0.30	1.07
12/11/01	4097-14	8th Floor: Northeast Opposite Windows	0.12	0.12	0.60	0.77	1.01	0.18	0.30	1.07
12/11/01	4097-15	Roof: East End	0.12	0.53	0.60	0.30	1.01	0.18	0.30	1.07
12/11/01	4098-16	Roof: South East	0.12	0.42	0.60	0.95	1.01	0.18	0.30	1.07

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/12/01	2172-01	4th Floor: Reception Area	0.07	0.49	3.19	1.94	0.59	0.10	0.17	0.63
12/12/01	2172-02	4th Floor: Corridor Adj. To Generator Room	0.07	0.49	1.46	1.53	0.59	0.10	0.17	0.80
12/12/01	2172-03	4th Floor: In Comp Room Opposite Window	0.07	0.49	0.87	1.25	0.59	0.10	0.17	0.63
12/12/01	2172-04	4th Floor: South East Corner	0.01	0.04	0.07	0.06	0.06	0.01	0.02	0.06
12/12/01	2172-05	4th Floor: In Cash Check Room	0.69	0.52	0.90	1.94	0.59	0.10	0.17	0.87
12/12/01	6414-06	4th Floor: Inside Accounting Room	0.07	0.49	0.56	0.83	0.59	0.10	0.17	0.63

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Rosnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/12/01	6414-07	6th Floor: Reception Area	0.07	0.38	6.28	0.94	0.59	0.10	0.17	1.60
12/12/01	6414-08	6th Floor: Opposite Stairwell X	0.07	0.35	0.69	3.85	0.59	0.10	0.17	0.80
12/12/01	6414-09	6th Floor: Office Area	0.07	0.35	0.45	0.66	0.59	0.10	0.17	1.46
12/12/01	6414-10	6th Floor: Office Area Outside Storage Room	0.07	0.35	0.35	0.87	0.59	0.10	0.17	0.63
12/12/01	2176-11	6th Floor: South West Office Area	0.10	0.49	1.41	0.66	0.59	0.10	0.17	0.73
12/12/01	2176-12	6th Floor: Outside Conf. Room Office Area	0.07	0.42	0.69	1.25	0.59	0.10	0.17	0.63
12/12/01	2176-13	6th Floor: N.E. Corner Office Area	0.07	0.31	0.63	0.42	0.59	0.10	0.17	0.63
12/12/01	2176-14	6th Floor: Opposite East Pantry	0.07	0.66	0.45	1.18	0.59	0.10	0.17	0.63

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/12/01	2176-15	Roof: North East Corner	0.07	0.24	0.42	0.17	0.59	0.10	0.17	0.63
12/12/01	2176-16	Roof: East Side	0.07	0.59	0.35	0.21	0.59	0.10	0.17	0.63

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10863

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/13/01	5272-05	Basement Corridor	0.09	0.23	0.46	3.70	0.79	0.14	0.23	0.83
12/13/01	5272-02	Basement Donnelly Print Shop Central Area	0.09	0.46	0.56	5.74	0.79	0.14	0.23	0.83
12/13/01	5272-01	Basement Donnelly Print Shop East End	0.09	0.56	0.69	0.93	0.79	0.14	0.23	0.83
12/13/01	5272-03	Basement Donnelly Print Shop West End	0.09	0.28	0.56	6.53	0.79	0.14	0.23	0.83
12/13/01	5274-07	Basement Gas Meter Room	0.09	0.28	0.46	5.97	0.79	0.14	0.23	0.83
12/13/01	5272-04	Basement Inside Pump Room	0.09	0.28	0.46	6.02	0.79	0.14	0.23	0.83
12/13/01	5274-06	Basement Steam Meter Room	0.09	0.42	0.46	11.16	0.79	0.14	0.23	0.83

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/13/01	5278-016	2nd Floor: Corridor Adjacent To Mechanical Room	0.09	0.42	0.46	9.17	0.79	0.14	0.23	0.83
12/13/01	5277-015	2nd Floor: Donnelley & Son Reception Area	0.09	0.56	0.46	1.81	0.79	0.14	0.23	0.83
12/13/01	5278-018	2nd Floor: Inside Training Room	0.09	1.53	0.46	6.94	0.79	0.14	0.23	0.83
12/13/01	5279-021	2nd Floor: Office Area Opposite V. Cosgriff Office	0.09	0.65	0.88	10.46	0.79	0.14	0.23	0.83
12/13/01	5278-019	2nd Floor: Reception, Donnelley Services	0.09	0.69	0.46	3.66	0.79	0.14	0.23	0.83
12/13/01	5278-020	2nd Floor: Southeast, Donnelley & Son	0.09	0.32	0.46	11.02	0.79	0.14	0.23	0.83
12/13/01	5278-017	2nd Floor: Vacant Space Central Area	0.09	0.42	0.46	7.69	0.79	0.14	0.23	0.83

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10866

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/13/01	5277-012	3rd Floor: Adjacent To Conference Room "H"	0.09	0.23	0.46	6.34	0.79	0.14	0.23	0.83
12/13/01	5277-011	3rd Floor: Corridor Adjacent To Conference Room "D"	0.09	0.51	0.69	2.50	0.79	0.14	0.23	0.83
12/13/01	5277-013	3rd Floor: Corridor Opposite UPS Room	0.09	0.32	0.46	4.95	0.79	0.14	0.23	0.83
12/13/01	5277-014	3rd Floor: In Training Room	0.09	0.60	0.46	0.23	0.79	0.14	0.23	0.83
12/13/01	5274-08	3rd Floor: Reception Area	0.09	0.23	0.46	9.44	0.79	0.14	0.23	0.83
12/13/01	5274-09	3rd Floor: Southwest Kitchen	0.09	0.48	0.46	1.39	0.79	0.14	0.23	0.83
12/13/01	5274-10	3rd Floor: Southwest Lounge Area	0.09	0.42	0.46	9.31	0.79	0.14	0.23	0.83

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Data Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/13/01	5275-028	9th Floor: Adjacent To Exit "W", Stair "X"	0.09	0.46	0.46	2.96	0.79	0.14	0.23	0.83
12/13/01	5275-029	9th Floor: Northeast Corner	0.09	0.37	0.46	3.98	0.79	0.14	0.23	0.83
12/13/01	5279-025	9th Floor: Northside Adjacent To Window	0.09	0.28	0.46	3.01	0.79	0.14	0.23	0.83
12/13/01	5275-030	9th Floor: Office Area Southwest Corner	0.09	0.42	0.46	4.12	0.79	0.14	0.23	0.83
12/13/01	5275-026	9th Floor: Opposite Computer Room	0.09	0.37	0.46	5.05	0.79	0.14	0.23	0.83
12/13/01	5275-027	9th Floor: Opposite Pantry	0.09	0.37	0.46	2.50	0.79	0.14	0.23	0.83
12/13/01	5279-024	9th Floor: Reception Area	0.09	0.37	0.46	7.41	0.79	0.14	0.23	1.53

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10885

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/13/01	S279-022	Roof: Eastside	0.09	0.46	0.46	1.34	0.79	0.14	0.23	0.83
12/13/01	S279-023	Roof: Southeast	0.09	0.32	0.46	2.78	0.79	0.14	0.23	0.83

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/20/01	1058-01	Loading Dock Adjacent to Booth	0.05	0.57	0.39	5.42	0.44	0.08	0.13	0.47
12/20/01	1058-02	Loading Dock at Entrance to Street	0.08	0.48	0.44	4.45	0.44	0.08	0.13	1.07
12/20/01	1058-03	Parking Garage Near Back Exit Upper Level	0.05	0.78	0.39	1.12	0.44	0.08	0.13	0.47
12/20/01	1058-04	Parking Garage Adjacent to Soda Machine Upper Level	0.08	0.57	0.34	1.80	0.44	0.08	0.13	0.47
12/20/01	1058-05	Parking Garage Southend Lower Level	0.08	0.36	0.57	1.22	0.44	0.08	0.18	0.47
12/20/01	1059-06	Parking Garage Northend Lower Level	0.05	0.42	0.44	1.51	0.44	0.08	0.13	0.47

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/27/01	6061-01	10th Floor: IWA/Northside	0.00	0.01	0.07	0.06	0.02	0.00	0.01	0.03
12/27/01	6061-02	10th Floor: IWA/Southside	0.00	0.01	0.12	0.07	0.03	0.00	0.01	0.11
12/27/01	6061-03	10th Floor: IWA/Westside	0.00	0.01	0.07	0.06	0.03	0.00	0.01	0.07
12/27/01	6061-04	10th Floor: IWA/Eastside	0.00	0.01	0.05	0.04	0.02	0.00	0.01	0.05
12/27/01	6061-05	10th Floor: IWA/Middle Area	0.00	0.01	0.05	0.07	0.02	0.00	0.01	0.05
12/27/01	6062-06	10th Floor: IWA/Southwest Corner Opposite Window	0.00	0.01	0.04	0.04	0.02	0.00	0.01	0.04
12/27/01	6062-07	10th Floor: IWA/Northwest Corner Opposite Window	0.00	0.01	0.08	0.11	0.03	0.00	0.01	0.10
12/27/01	6062-08	Roof: OWA/Northeast Corner	0.00	0.01	0.05	0.03	0.02	0.00	0.01	0.04
12/27/01	6062-09	Roof: OWA/Northside	0.00	0.01	0.08	0.06	0.05	0.00	0.01	0.16