

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT**PROJECT:** 211658**DATE COLLECTED:** 11/17/01**CLIENT:** Jack Resnick & Sons**DATE RECEIVED:** 11/18/01**ADDRESS:** 75 Park Place**DATE ANALYZED:** 11/20/01**DESCRIPTION:** Lobby northwest side by passenger elevators

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40288	211658-02	CADMIUM	0.2
		CHROMIUM	0.5
		COPPER	4.3
		IRON	43.9
		LEAD	0.5
		MANGANESE	3.4
		NICKEL	0.5
		SILICA	34.5
		ZINC	26.8

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT

PROJECT: 211658

DATE COLLECTED: 11/17/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/18/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/20/01

DESCRIPTION: Lobby inside ceiling plenum southside

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40289	211658-03	CADMIUM	0.2
		CHROMIUM	0.8
		COPPER	6.6
		IRON	93.3
		LEAD	0.3
		MANGANESE	3.8
		NICKEL	0.5
		SILICA	58.5
		ZINC	48.2

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT

PROJECT: 211658

DATE COLLECTED: 11/17/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/18/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/20/01

DESCRIPTION: Lobby inside ceiling plenum westside

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40290	211658-04	CADMIUM	1
		CHROMIUM	3
		COPPER	38
		IRON	429
		LEAD	4
		MANGANESE	19
		NICKEL	1
		SILICA	277
		ZINC	144

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT

PROJECT: 211658

DATE COLLECTED: 11/17/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/18/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/20/01

DESCRIPTION: Loading dock floor adjacent to the ramp

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40291	211658-05	CADMIUM	0.2
		CHROMIUM	1.7
		COPPER	12.3
		IRON	1110.0
		LEAD	0.9
		MANGANESE	11.2
		NICKEL	0.3
		SILICA	85.2
		ZINC	122.0

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT

PROJECT: 211658

CLIENT: Jack Resnick & Sons

ADDRESS: 75 Park Place

DATE COLLECTED: 11/17/01

DATE RECEIVED: 11/18/01

DATE ANALYZED: 11/20/01

DESCRIPTION: Loading dock southwest wall

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40292	211658-06	CADMIUM	0
		CHROMIUM	1
		COPPER	5
		IRON	157
		LEAD	0
		MANGANESE	3
		SILICA	39
		ZINC	36

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT

PROJECT: 211658

DATE COLLECTED: 11/17/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/18/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/20/01

DESCRIPTION: Loading dock floor entrance adjacent to the gate

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40293	211658-07	CADMIUM	0.8
		CHROMIUM	10.4
		COPPER	159.0
		IRON	3600.0
		LEAD	49.7
		MANGANESE	89.2
		NICKEL	4.1
		SILICA	625.0
		ZINC	364.0

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

METAL WIPE LABORATORY DATA REPORT

PROJECT: 211658

DATE COLLECTED: 11/17/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/18/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/20/01

DESCRIPTION: Inside ceiling plenum south access hatch.

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40294	211658-08	CADMIUM	0.2
		CHROMIUM	0.6
		COPPER	5.6
		IRON	93.9
		LEAD	0.5
		MANGANESE	3.5
		NICKEL	0.5
		SILICA	49.1
		ZINC	40.2

AMBIENT GROUP
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

LEAD WIPE LABORATORY DATA REPORT

PROJECT: 211542

DATE COLLECTED: 11/27/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/28/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/28/01

DESCRIPTION: Lobby Concierge Desk

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/ft2)
40738	75P-MTL-1	CADMIUM	<0.2
		CHROMIUM	0.2
		COPPER	7.2
		LEAD	<1.7
		NICKEL	<0.5
		ZINC	46.2

MDL = 0.1 ug/m3 based upon a one (1) cubic meter (m3) sample volume.
ND = Not Detected

AMBIENT GROUP
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP # 10865

LEAD WIPE LABORATORY DATA REPORT

PROJECT: 211542

DATE COLLECTED: 11/27/01

CLIENT: Jack Resnick & Sons

DATE RECEIVED: 11/28/01

ADDRESS: 75 Park Place

DATE ANALYZED: 11/28/01

DESCRIPTION: Lobby Back room by Freight Elevator B

LABORATORY ID	FIELD ID	ANALYTE	METAL FOUND on WIPE (ug/R2)
40739	75P-MTL-2	CADMIUM	0.3
		CHROMIUM	2.8
		COPPER	22.2
		LEAD	8.3
		NICKEL	1.4
		ZINC	284.0

MDL = 0.1 ug/m3 based upon a one (1) cubic meter (m3) sample volume.
ND = Not Detected

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PAR-01	12/7/01	5th Floor: Reception Area/Desk	0.20	0.30	9.20	44.40	1.70	2.10	0.70	39.40
75PAR-02	12/7/01	5th Floor: Mulex Corn Office/Desk	0.20	0.20	6.20	10.50	1.70	0.30	0.50	43.30
75PAR-03	12/7/01	5th Floor: South East Corner/Windowsill	0.20	0.20	5.80	31.50	1.70	0.40	0.50	29.30
75PAR-04	12/7/01	5th Floor: Storage Room/Cabinet Top	0.20	0.20	6.10	16.60	1.70	0.30	0.50	12.30
75PAR-05	12/7/01	5th Floor: N.W. Corner/Window Sill	0.20	0.20	5.80	28.40	1.70	0.60	0.50	32.70
75PAR-06	12/7/01	5th Floor: Opposite Com. Room/Desk	0.20	0.20	8.30	109.00	1.70	0.90	0.50	31.80
75PAR-07	12/7/01	5th Floor: N.W. Corner/Window Sill	0.20	0.20	6.20	12.60	1.70	0.30	0.50	8.40

Ambiant Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
7SPAR -08	12/7/01	4th Floor: Reception Area/Desk	0.20	0.20	5.80	30.40	1.70	0.40	0.50	13.60
7SPAR -09	12/7/01	4th Floor: Inside Computer Room/Desk	0.20	0.20	8.00	21.90	1.70	0.40	0.50	22.10
7SPAR -10	12/7/01	4th Floor: Opposite Generator Room/Floor	0.20	0.20	5.50	13.50	1.70	0.30	0.50	43.10
7SPAR -11	12/7/01	4th Floor: N.W. Corner/Window Sill	0.20	0.30	6.30	23.20	1.70	1.30	1.20	56.30
7SPAR -12	12/7/01	4th Floor: Trading Floor/Desk	0.20	0.20	11.00	41.00	1.70	0.80	0.60	46.00
7SPAR -13	12/7/01	4th Floor: Corridor/Wall	0.20	0.20	5.10	30.10	1.70	0.90	1.60	100.00
7SPAR -14	12/7/01	4th Floor: Accountant Office/Desk	0.20	0.20	9.30	28.50	1.70	0.90	0.50	34.70

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75Park-01	12/27/01	10th Floor: Southside Top of Desk	0.005	0.022	0.105	0.312	0.017	0.018	0.012	0.919
75Park-02	12/27/01	10th Floor: Northside Top of Radiator	0.008	0.028	0.136	0.381	0.035	0.026	0.019	0.719
75Park-03	12/27/01	10th Floor: Westside Top of Radiator	0.006	0.010	0.081	0.269	0.019	0.015	0.022	0.292
75Park-04	12/27/01	10th Floor: Eastside Top of Desk	0.005	0.010	0.087	0.310	0.017	0.016	0.013	0.281
75Park-05	12/27/01	10th Floor: Middle Area Top of Desk	0.004	0.011	0.093	0.354	0.021	0.017	0.013	0.466
75Park-06	12/27/01	10th Floor: Southwest Top of Radiator	0.004	0.011	0.109	0.416	0.025	0.019	0.010	0.46
75Park-07	12/27/01	10th Floor: Northwest Top of Radiator	0.006	0.014	0.153	0.474	0.040	0.021	0.017	0.53

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/lit							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PAR-01	12/12/01	7th Floor: South East Opposite Cor. Room Desk	0.2	0.4	5.1	13.0	1.7	0.6	0.5	5.30
75PAR-02	12/12/01	7th Floor: Reception Area Desk	0.2	0.3	4.4	11.5	1.7	0.5	0.5	3.00
75PAR-03	12/12/01	7th Floor: Near Stairwell X Floor	0.2	0.3	4.8	16.1	1.7	0.5	0.5	6.00
75PAR-04	12/12/01	7th Floor: Near Copy Machine Desk	0.2	0.5	7.6	35.8	1.7	1.2	0.5	11.00
75PAR-05	12/12/01	7th Floor: North Side Desk	0.2	0.7	7.3	16.2	2.1	0.8	0.5	5.30
75PAR-06	12/12/01	7th Floor: North East Section Desk	0.2	0.2	6.2	24.5	1.7	0.9	0.5	8.00
75PAR-07	12/12/01	7th Floor: Adj. To Computer Room Floor	0.2	0.4	5.8	22.5	1.7	0.9	0.5	7.90

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft2							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
7SPARK- 01	12/10/01	11th Floor: Southend Interior Window Sill	0.40	0.70	6.20	45.30	1.70	3.50	0.50	20.00
7SPARK- 02	12/10/01	11th Floor: Northend Interior Window Sill	0.40	0.20	5.70	1.59	1.70	1.30	0.50	12.30
7SPARK- 03	12/10/01	11th Floor: Eastend Interior Window Sill	0.30	1.10	12.30	116.00	1.70	10.10	0.50	49.40
7SPARK- 04	12/10/01	11th Floor: Westend Interior Window Sill	0.20	0.20	5.80	26.90	1.70	1.00	0.80	37.10
7SPARK- 05	12/10/01	11th Floor: Southwest Corner Interior Window Sill	0.20	0.30	4.30	31.90	1.70	2.30	0.50	18.30
7SPARK- 06	12/10/01	11th Floor: Elevator Lobby And Floor	0.20	0.20	5.40	33.50	1.70	1.90	0.50	18.90
7SPARK- 07	12/10/01	11th Floor: Central Area Column								
7SPARK- 08	12/10/01	10th Floor: Centralwest Desk	0.20	0.20	7.20	32.70	1.70	1.20	0.70	29.50

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft2							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PARK- 09	12/10/01	10th Floor: Central Desk	0.20	0.20	4.80	25.00	1.70	1.50	1.00	47.30
75PARK- 10	12/10/01	10th Floor: Centraleast Desk	0.20	0.20	5.30	15.20	1.70	0.90	0.50	12.50
75PARK- 11	12/10/01	10th Floor: Southeast Desk	0.30	0.40	5.10	37.80	1.70	3.70	0.50	23.00
75PARK- 12	12/10/01	10th Floor: Northend Window Sill Interior	0.20	0.40	4.50	41.20	1.70	3.50	0.50	20.20
75PARK- 13	12/10/01	10th Floor: Eastside Window Sill Interior	0.20	0.20	3.50	23.80	1.70	1.30	0.50	21.10
75PARK- 14	12/10/01	10th Floor: Westside Window Sill Interior	0.20	0.20	5.50	20.30	1.70	0.70	0.50	31.30
75PARK- 15	12/10/01	9th Floor: Southeast Desk	0.20	0.30	5.40	18.80	1.70	0.70	0.50	19.20

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 21658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/lit							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PARK- 16	12/10/01	9th Floor: Southwest Corner Desk	0.20	0.20	4.30	14.20	1.70	0.50	0.50	19.10
75PARK- 17	12/10/01	9th Floor: Reception Area Desk	0.20	0.20	4.90	17.00	1.70	0.50	0.50	24.50
75PARK- 18	12/10/01	9th Floor: Northside Desk	0.30	0.20	6.50	25.60	1.70	0.70	0.50	29.70
75PARK- 19	12/10/01	9th Floor: Northwest Corner Desk	0.20	0.20	8.80	25.50	1.70	0.70	0.50	27.20
75PARK- 20	12/10/01	9th Floor: Corridor Floor	0.20	0.20	5.30	18.90	1.70	0.40	0.50	19.30
75PARK- 21	12/10/01	9th Floor: Southwest Pantry Desk	0.40	0.30	5.50	14.40	1.70	0.60	0.90	20.20
75PARK- 22	12/10/01	8th Floor: Reception Area Desk	0.20	0.20	3.80	22.60	1.70	0.40	0.50	18.40

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PARK- 23	12/10/01	8th Floor: Northside Window Sill	0.20	0.20	5.40	24.30	1.70	0.50	0.50	19.40
75PARK- 24	12/10/01	8th Floor: Opposite Com. Room Desk	0.20	0.20	3.80	12.10	1.70	0.50	0.50	13.40
75PARK- 25	12/10/01	8th Floor: Northeast Corner Window Sill	0.30	0.20	4.00	21.20	1.70	0.70	0.80	20.90
75PARK- 26	12/10/01	8th Floor: Southwest Section Desk	0.30	0.20	3.60	16.80	1.70	0.40	1.30	18.80
75PARK- 27	12/10/01	8th Floor: Central Area Desk	0.40	0.20	7.10	22.70	1.70	0.70	0.70	24.40
75PARK- 28	12/10/01	8th Floor: Southwest Corner Table Top	0.30	0.20	4.90	19.90	1.70	0.70	0.60	33.20

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7500 method)

Client: Jack Reppik & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported in ug/R2							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75Pmk-01	12/13/01	2nd Floor: Reception Area Desk	0.70	1.00	6.40	18.20	2.00	1.00	1.20	14.60
75Pmk-02	12/13/01	2nd Floor: Corridor Adjacent to HRM Room Floor	0.20	0.40	5.10	19.80	1.70	0.80	0.50	8.90
75Pmk-03	12/13/01	2nd Floor: Vacant Space Cabinet Top	0.50	0.80	5.50	20.00	2.80	0.80	0.50	10.40
75Pmk-04	12/13/01	2nd Floor: Training Room Desk	0.10	0.50	2.90	11.30	1.70	0.60	0.50	5.50
75Pmk-05	12/13/01	2nd Floor: Dormitory Service Office Desk	0.10	0.40	3.40	12.40	1.70	0.60	0.50	7.50
75Pmk-06	12/13/01	2nd Floor: Dormitory & Sorts Office Middle Area Desk	0.20	0.30	2.10	9.40	1.70	0.40	0.50	4.70
75Pmk-07	12/13/01	2nd Floor: Northrest Corner Desk	0.20	0.10	3.80	16.60	1.70	0.60	0.50	8.00

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported in ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75Park-01	12/13/01	2nd Floor: Reception Area Desk	0.70	1.00	6.40	18.20	2.00	1.00	1.20	14.60
75Park-02	12/13/01	2nd Floor: Corridor Adjacent to NER Room Floor	0.20	0.40	5.30	19.80	1.70	0.80	0.50	8.90
75Park-03	12/13/01	2nd Floor: Vacant Space Cabinet Top	0.50	0.80	5.50	20.00	2.80	0.80	0.50	10.40
75Park-08	12/13/01	3rd Floor: Reception Area	0.30	0.50	4.00	19.30	1.70	0.50	6.60	10.20
75Park-09	12/13/01	3rd Floor: Kitchen Table	0.30	0.40	6.90	3.90	16.50	0.60	7.00	9.60
75Park-10	12/13/01	3rd Floor: Lounge Area Window Sill	0.40	0.50	3.80	10.60	1.70	0.60	0.60	0.80
75Park-11	12/13/01	3rd Floor: Office Adjacent to Conference Room 10' Floor	0.60	1.00	6.00	18.60	1.70	1.10	1.20	12.60
75Park-12	12/13/01	3rd Floor: Office Adjacent to Conference Room 14' Floor	0.20	0.40	3.50	15.10	1.70	0.50	0.50	6.90
75Park-13	12/13/01	3rd Floor: Training Room Desk	0.20	0.30	3.10	10.60	1.70	0.30	0.50	5.90
75Park-14	12/13/01	3rd Floor: Adjacent to UPS Office Floor	0.30	0.50	3.50	12.10	1.70	0.50	0.50	11.70

Ambient Group, Inc.
55 West 34th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/lr2							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75Park-01	12/13/01	2nd Floor: Reception Area Desk	0.70	1.00	6.40	18.20	2.00	1.00	1.20	14.60
75Park-02	12/13/01	2nd Floor: Corridor Adjacent to ATR Room Floor	0.20	0.40	5.30	19.80	1.70	0.80	0.50	8.90
75Park-03	12/13/01	2nd Floor: Vacant Space Cabinet Top	0.50	0.80	5.50	20.00	2.80	0.40	0.50	10.40
75Park-15	12/13/01	Basement: Dunsley Print Shop West Desk	0.40	0.60	4.40	15.00	1.70	0.70	0.60	9.30
75Park-16	12/13/01	Basement: Dunsley Print Shop Middle Floor	0.70	0.50	5.10	20.40	1.70	0.60	0.50	9.20
75Park-17	12/13/01	Basement: Dunsley Print Shop East Desk	0.40	0.50	2.90	10.30	1.70	0.50	0.50	5.90
75Park-18	12/13/01	Basement: Corridor Floor	0.20	0.50	4.00	15.90	1.70	0.60	0.50	9.50
75Park-19	12/13/01	Basement: Pump Room Floor	0.30	0.50	4.40	20.00	1.70	0.70	0.50	10.70
75Park-20	12/13/01	Basement: Gas Meter Room Floor	0.30	0.40	3.10	12.00	1.70	0.50	0.70	9.00
75Park-21	12/13/01	Basement: Steam Meter Room Floor	0.60	0.80	4.30	8.40	1.70	0.80	0.60	4.50

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PAR -01	12/6/01	14th Floor: Reception Area/Desk	0.20	0.20	4.80	51.70	1.70	4.50	0.50	18.50
75PAR -02	12/6/01	14th Floor: Northside/Wall	0.20	0.20	5.60	40.90	1.70	0.80	0.50	16.40
75PAR -03	12/6/01	14th Floor: Westside/Window Sill	0.20	0.20	4.70	25.20	1.70	0.50	0.50	14.60
75PAR -04	12/6/01	12th Floor: Large Office Area/North	0.20	0.20	4.10	22.80	1.70	0.50	0.50	9.70
75PAR -05	12/6/01	12th Floor: Large Office Area/N.W./Desk	0.20	0.20	6.50	41.50	2.20	1.00	0.50	16.50
75PAR -06	12/6/01	12th Floor: Large Office/Westend/Desk	0.20	0.20	6.30	53.10	1.70	2.50	0.50	29.10
75PAR -07	12/6/01	12th Floor: East Office Suite/Window Sill	0.20	0.20	4.90	15.50	1.70	0.70	0.50	9.30
75PAR -08	12/6/01	12th Floor: West Office Suite	0.20	0.20	5.30	29.90	1.70	0.60	0.50	13.20
75PAR -09	12/6/01	6th Floor: Reception Area/Desk	0.20	0.20	6.30	32.50	1.70	0.60	0.50	14.10
75PAR -10	12/6/01	6th Floor: Store Room Cabinet Top	0.20	0.20	4.50	23.10	1.70	0.60	0.50	12.20
75PAR -11	12/6/01	6th Floor: East Side Window Sill	0.20	0.20	4.70	34.10	1.70	0.60	0.50	11.60
75PAR -12	12/6/01	6th Floor: North East Office Area/ Desk	0.20	0.20	3.20	16.00	1.70	0.30	0.50	5.80
75PAR -13	12/6/01	6th Floor: Office Area Adj. to Conference Room/Desk	0.20	0.20	4.30	20.60	1.70	0.50	0.50	8.10
75PAR -14	12/6/01	6th Floor: In Small Conference Room/Table Top	0.20	0.20	4.00	42.20	1.70	0.90	0.50	11.90
75PAR -15	12/6/01	6th Floor: Opposite Pantry/Desk	0.20	0.20	6.10	35.20	1.70	0.60	0.50	34.80

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Russett & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/L2							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75PARK- 28	12/20/01	Loading Dock Opposite Guard Booth	0.60	1.20	10.90	113.00	9.80	5.30	1.20	37.7
75PARK- 29	12/20/01	Loading Dock Entrance To Street	0.60	1.70	12.40	692.00	2.20	9.80	1.10	51.4
75PARK- 30	12/20/01	Parking Garage Upper Level	0.80	5.90	31.60	973.00	14.60	27.60	2.50	202
75PARK- 31	12/20/01	Parking Garage Upper Level	0.50	3.70	10.30	330.00	3.60	8.60	1.70	60.4
75PARK- 32	12/20/01	Parking Garage Lower Level - South	0.50	3.20	23.30	628.00	6.30	25.00	1.70	187
75PARK- 33	12/20/01	Parking Garage Lower Level - North	0.50	3.20	10.30	390.00	1.80	9.10	1.10	55.30

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft2							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75Park-01	12/27/01	10th Floor: Southside Top of Desk	0.01	0.02	0.11	0.31	0.02	0.02	0.01	0.919
75Park-02	12/27/01	10th Floor: Northside Top of Radiator	0.01	0.03	0.14	0.38	0.04	0.03	0.02	0.719
75Park-03	12/27/01	10th Floor: Westside Top of Radiator	0.01	0.01	0.08	0.27	0.02	0.02	0.02	0.292
75Park-04	12/27/01	10th Floor: Eastside Top of Desk	0.01	0.01	0.09	0.31	0.02	0.02	0.01	0.281
75Park-05	12/27/01	10th Floor: Middle Area Top of Desk	0.00	0.01	0.09	0.35	0.02	0.02	0.01	0.466
75Park-06	12/27/01	10th Floor: Southwest Top of Radiator	0.00	0.01	0.11	0.42	0.03	0.02	0.01	0.46
75Park-07	12/27/01	10th Floor: Northwest Top of Radiator	0.01	0.01	0.15	0.47	0.04	0.02	0.02	0.53