

03/04/2002 15:07 FAX 2129444618

AMBIENT GROUP

007



AMBIENT GROUP, INC.

10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-0009 - Fax: (516) 609-8271

Laboratory Report

AGL02147

Dust Characterization Laboratory Data Report

Client: Jack Resnick & Sons
Address: 75 Park Place
New York, NY
Collected By: Craig Kamback
Collected: 02/26/2002

Job Number: 220209
Date Received: 02/27/2002
Date Analyzed: 2/27/02
Job Location: 75 Park Place

Lab ID Field ID	Sample Location	Constituents	Percent of Sample **
0002147-001	E/Server Room/Cleaned/ Top of Cabinet A06	Cellulose	10
		Decayed Organic Matter	80
		Gravel Road Dust	10
			100
0002147-002	E/Server Room/Cleaned/Top of HVAC DAP II	Carbon Particles	20
		Cellulose	10
		Decayed Organic Matter	40
		Gravel Road Dust	30
			100
0002147-003	W/Slave Rm/Uncleaned/Metal Shelf/ 3rd Bottom Shelf	Carbon Particles	20
		Fiber Glass	40
		Gravel Road Dust	40
			100
0002147-004	E/Server Rm/Cleaned/Cntr of Rm/Top of Fixture	Carbon Particles	10
		Cellulose	20
		Decayed Organic Matter	10
		Fiber Glass	10
		Gravel Road Dust	50
			100

SIGNED FOR AMBIENT GROUP, INC. BY:

03/04/2002 15:08 FAX 2129444618

AMBIENT GROUP

008

**AMBIENT GROUP, INC.**10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-0009 - Fax: (516) 609-8271

Laboratory Report

AGL02141

Metals ProfileClient: Jack Resnick & Sons
Address: 75 Park Place
New York, NY
Collected By: Craig Kamback
Collected: 02/26/2002 9:17Job Number: 220209
Date Received: 02/27/2002
Date Analyzed: 02/27/2002
Job Location: 75 Park PlaceLab ID: 0002141-001
Field ID:
Location: E/Server Room/Cleaned/Top of CabinetMatrix: WIPE
Area Wiped: 144

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>LOC</u>	<u>Flag</u>
Cadmium	< 0.198	µg/ft ²	0.9	
Chromium	1.69	µg/ft ²	46.5	
Copper	4.84	µg/ft ²	93.0	
Iron	52.0	µg/ft ²	N/A	
Lead	1.78	µg/ft ²	40.0	
Manganese	< 0.30	µg/ft ²	N/A	
Nickel	< 0.50	µg/ft ²	140.0	
Zinc	128	µg/ft ²	930	

LOC = Limit of Contamination

Page 1 of 4

**AMBIENT GROUP, INC.**

10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-0009 - Fax: (516) 609-8271

Laboratory Report
AGL02141

Metals Profile

Client: Jack Resnick & Sons
Address: 75 Park Place
New York, NY
Collected By: Craig Kamback
Collected: 02/26/2002 9:17

Job Number: 220209
Date Received: 02/27/2002
Date Analyzed: 02/27/2002
Job Location: 75 Park Place

Lab ID: 0002141-002
Field ID:
Location: E/Server Room/Cleaned Top of HVAC Unit D

Matrix: WIPE
Area Wiped: 144

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>LOC</u>	<u>Flag</u>
Cadmium	0.198	µg/ft ²	0.9	
Chromium	1.69	µg/ft ²	46.5	
Copper	33.1	µg/ft ²	93.0	
Iron	59.8	µg/ft ²	N/A	
Lead	1.98	µg/ft ²	40.0	
Manganese	0.50	µg/ft ²	N/A	
Nickel	< 0.50	µg/ft ²	140.0	
Zinc	200	µg/ft ²	930	

LOC = Limit of Contamination

Page 2 of 4

**AMBIENT GROUP, INC.**

10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-0009 - Fax: (516) 609-8271

Laboratory Report

AGL02141**Metals Profile**

Client: Jack Resnick & Sons
Address: 75 Park Place
New York, NY
Collected By: Craig Kamback
Collected: 02/26/2002 9:17

Job Number: 220209
Date Received: 02/27/2002
Date Analyzed: 02/27/2002
Job Location: 75 Park Place

Lab ID: 0002141-003
Field ID:
Location: W/Slave Room/Uncleaned Metal Shelf/Botto

Matrix: WIPE
Area Wiped: 144

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>LOC</u>	<u>Flag</u>
Cadmium	0.598	µg/f2	0.9	
Chromium	4.59	µg/f2	46.5	
Copper	23.2	µg/f2	93.0	
Iron	1300	µg/f2	N/A	
Lead	13.5	µg/f2	40.0	
Manganese	23.5	µg/f2	N/A	
Nickel	0.90	µg/f2	140.0	
Zinc	214	µg/f2	930	

LOC = Limit of Contamination

Page 3 of 4

**AMBIENT GROUP, INC.**

10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-0009 - Fax: (516) 609-8271

Laboratory Report

AGL02141**Metals Profile**

Client: Jack Resnick & Sons
Address: 75 Park Place
New York, NY
Collected By: Craig Kamback
Collected: 02/26/2002 9:17

Job Number: 220209
Date Received: 02/27/2002
Date Analyzed: 02/27/2002
Job Location: 75 Park Place

Lab ID: 0002141-004
Field ID:
Location: E/Server Room/Cleaned/Center of Room/Ligh

Matrix: WIPE
Area Wiped: 144

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>LOC</u>	<u>Flag</u>
Cadmium	0.698	µg/ft ²	0.9	
Chromium	7.69	µg/ft ²	46.5	
Copper	337	µg/ft ²	93.0	>LOC
Iron	772	µg/ft ²	N/A	
Lead	7.58	µg/ft ²	40.0	
Manganese	32.6	µg/ft ²	N/A	
Nickel	5.4	µg/ft ²	140.0	
Zinc	470	µg/ft ²	930	

SIGNED FOR AMBIENT GROUP, INC. BY:

LOC = Limit of Contamination

Page 4 of 4