

AMBIENT LABS, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542
ELAP #10865

METAL AIR LABORATORY DATA REPORT

Client: Jack Resnick & Sons

Client Address: 75 Park Place

Project ID : 211658

Date Collected	Field ID	Description	Concentrations Reported In ug/m ³							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
12/27/01	6061-01	10th Floor: IWA/Northside	0.00	0.01	0.07	0.06	0.02	0.00	0.01	0.03
12/27/01	6061-02	10th Floor: IWA/Southside	0.00	0.01	0.12	0.07	0.03	0.00	0.01	0.11
12/27/01	6061-03	10th Floor: IWA/Westside	0.00	0.01	0.07	0.06	0.03	0.00	0.01	0.07
12/27/01	6061-04	10th Floor: IWA/Eastside	0.00	0.01	0.05	0.04	0.02	0.00	0.01	0.05
12/27/01	6061-05	10th Floor: IWA/Middle Area	0.00	0.01	0.05	0.07	0.02	0.00	0.01	0.05
12/27/01	6062-06	10th Floor: IWA/Southwest Corner Opposite Window	0.00	0.01	0.04	0.04	0.02	0.00	0.01	0.04
12/27/01	6062-07	10th Floor: IWA/Northwest Corner Opposite Window	0.00	0.01	0.08	0.11	0.03	0.00	0.01	0.10
12/27/01	6062-08	Roof: OWA/Northeast Corner	0.00	0.01	0.05	0.03	0.02	0.00	0.01	0.04
12/27/01	6062-09	Roof: OWA/Northside	0.00	0.01	0.08	0.06	0.05	0.00	0.01	0.16