

Metal Wipes Report
(Analysis via NIOSH 7300 method)

Ambient Group, Inc.
55 West 39th Street
New York, NY 10018

Client: Jack Resnick & Sons
Address: 75 Park Place
Project ID: 211658

Field ID	Date Collected	Floor/Location	Concentrations Reported In ug/ft ²							
			Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
75Park-01	12/27/01	10th Floor: Southside Top of Desk	0.01	0.02	0.11	0.31	0.02	0.02	0.01	0.919
75Park-02	12/27/01	10th Floor: Northside Top of Radiator	0.01	0.03	0.14	0.38	0.04	0.03	0.02	0.719
75Park-03	12/27/01	10th Floor: Westside Top of Radiator	0.01	0.01	0.08	0.27	0.02	0.02	0.02	0.292
75Park-04	12/27/01	10th Floor: Eastside Top of Desk	0.01	0.01	0.09	0.31	0.02	0.02	0.01	0.281
75Park-05	12/27/01	10th Floor: Middle Area Top of Desk	0.00	0.01	0.09	0.35	0.02	0.02	0.01	0.466
75Park-06	12/27/01	10th Floor: Southwest Top of Radiator	0.00	0.01	0.11	0.42	0.03	0.02	0.01	0.46
75Park-07	12/27/01	10th Floor: Northwest Top of Radiator	0.01	0.01	0.15	0.47	0.04	0.02	0.02	0.53