

METALS IN AIR

Ambient Group, Inc.
55 West 39th Street, 12th Floor
New York, New York 10018

Client: Jack Resnick & Sons
 75 Park Place
 New York, New York 10007

Project ID # 211358
 Project Address: 75 Park Place
 Survey Date: 01/06/01

Floor/Location	Concentrations Reported In ug/m ³							
	Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
8th floor/SW Corner	<0.22	0.66	<1.69	<14.93	<1.69	<0.51	<0.37	<1.76
7th floor/SW Corner	<0.22	0.37	<1.69	<14.93	<1.69	<0.51	<0.37	<1.76
6th floor/SW Corner	<0.22	0.59	<1.70	<15.01	<1.70	<0.52	<0.37	<1.78
5th floor/SW Corner	<0.21	0.56	<1.60	<14.1	<1.6	<0.49	<0.35	<1.67
4th floor/SW Corner	<0.21	0.83	<1.60	<14.10	<1.60	<0.49	<0.35	<1.67
3rd floor/SW Corner	<0.41	<1.24	<3.16	<27.88	<3.16	<0.96	<0.69	<3.30
2nd floor/SW Corner	<0.42	1.11	<3.19	<28.19	<3.19	<0.97	<0.69	<3.33
Lobby/Opposite Lobby Desk	<0.41	<0.82	<3.16	<27.88	<3.16	<0.96	<0.69	<3.30
Level CM/Mechanical Room	<0.41	0.82	<3.13	<27.58	<3.13	<0.95	<0.68	<3.26
Level C/Freight Elevator Lobby	<0.40	0.67	<3.09	<27.28	<3.09	<0.94	<0.67	<3.23
14th floor/SW Corner	<0.44	1.47	<3.38	<29.85	<3.38	<1.03	<0.74	<3.53
12th floor/SW Corner	<0.44	1.91	<3.38	<29.85	<3.38	<1.03	<0.74	<3.53
11th floor/SW Corner	<0.44	1.47	<3.38	<29.85	<3.38	<1.03	<0.74	<3.53
10th floor/SW Corner	<0.44	1.47	<3.38	<29.85	<3.38	<1.03	<0.74	<3.53
9th floor/SW Corner	<0.44	<0.29	<3.38	<29.85	<3.38	<1.03	<0.74	<3.53

All levels reported are below their associated standards and guidelines.

Standard/Guideline

OSHA PEL for Cadmium: 5ug/m3
 OSHA PEL for Chromium: 1000ug/m3
 OSHA PEL for Copper: 1000ug/m3
 OSHA PEL for Iron: 10000ug/m3
 OSHA PEL for Lead: 50ug/m3
 OSHA PEL for Manganese: 1000ug/m3
 OSHA PEL for Nickel: 1000ug/m3
 OSHA PEL for Zinc: 5000ug/m3