

Sent By: HP LaserJet 3100;

5166820248;

Oct-10-01 8:46AM;

Page 3

OCT-09-2001 07:23

SCIENTIFIC LABS

212 679 3336 F.M. 14

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8800 • FAX: (212) 679-8382

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nohlan Date Examined 10/05/2001 P.O. # N1-3529
 1600 Rt. 22 East Page 1 of 8
 Union, NJ 07083
 RE: N1-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/06/2001)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
JH-01	201101503-01	Yes	<1.5%
Location: Ground Floor, South Center			
Description: Gray, Homogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Materials: Cellulose 5.5%, Fibrous glass 35.5%, Non-fibrous >59.5%			
JH-02	201101503-02	Yes	<1.5%
Location: Ground Floor, Center			
Description: Gray, Homogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Materials: Cellulose 20.5%, Fibrous glass 30.5%, Non-fibrous >49.5%			
JH-03	201101503-03	Yes	<1.5%
Location: Ground Floor, North Center			
Description: Gray, Homogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Materials: Cellulose 15.5%, Fibrous glass 30.5%, Non-fibrous >54.5%			
JH-04	201101503-04	Yes	<1.5%
Location: Level 1, Southwest			
Description: Gray, Homogeneous, Debris			
Asbestos Type: Chrysotile Trace			
Other Materials: Cellulose 5.5%, Fibrous glass 35.5%, Non-fibrous 60.5%			
JH-05	201101503-05	Yes	<1.5%
Location: Level 1, Southwest			
Description: Gray, Homogeneous, Debris			
Asbestos Type: Chrysotile Trace			
Other Materials: Cellulose 5.5%, Fibrous glass 35.5%, Non-fibrous 60.5%			

RECEIVED: 10/10/01 8:40AM;

5188820248 -> *; Page 4

Sent By: HP LaserJet 3100;

5188820248;

Oct-10-01 8:46AM;

Page 4

OCT-09-2001 07:23

SCIENTIFIC LABS

212 679 9336 P.O. # 12

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-9336 • FAX: (212) 679-9332

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Data Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nehlsen Date Examined 10/05/2001 P.O. # N1-3529
 1600 Rt. 22 East Page 2 of 8
 Union, NJ 07083

RE: N1-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/08/2001)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
JH-06	201101503-06	Yes	<1.0%
Location: Level 1, Center			
Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile Trace Other Materials: Cellulose 5.0%, Fibrous glass 15.0%, Non-fibrous 60.0%			
JH-07	201101503-07	Yes	<1.0%
Location: Level 1, Northwest			
Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile Trace Other Materials: Cellulose 5.0%, Fibrous glass 35.0%, Non-fibrous 60.0%			
JH-08	201101503-08	Yes	<1.0%
Location: Level 1, Northwest			
Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1.0% Other Materials: Cellulose 10.0%, Fibrous glass 35.0%, Non-fibrous >54.0%			
JH-09	201101503-09	Yes	<1.0%
Location: Level 2, Southeast			
Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile Trace Other Materials: Cellulose 5.0%, Fibrous glass 35.0%, Non-fibrous 60.0%			
JH-10	201101503-10	Yes	<1.0%
Location: Level 2, Southwest			
Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1.0% Other Materials: Cellulose 10.0%, Fibrous glass 35.0%, Non-fibrous >54.0%			

Sent By: HP LaserJet 3100;

5106820248;

Oct-10-01 8:48AM;

Page 5

OCT-09-2001 87:23

SCIENTIFIC LABS

212 675 3392 P.04/12

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 675-0000 • FAX: (212) 675-0300

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nohlan Date Examined 10/05/2001 P.O. # NI-3529
 1600 Rt. 22 East
 Union, NY 07083

Page 3 of 8

RE: NI-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/02/2001)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
JH-11	201101503-11	Yes	<1. %

Location: Level 2, Center

Description: Grey, Homogeneous, Debris
 Asbestos Types: Chrysotile <1. %
 Other Material: Cellulose 5. %, Fibrous glass 33. %, Non-fibrous >59. %

JH-12	201101503-12	Yes	<1. %
-------	--------------	-----	-------

Location: Level 2, Northwest

Description: Grey, Homogeneous, Debris
 Asbestos Types: Chrysotile Trace
 Other Material: Cellulose 5. %, Fibrous glass 35. %, Non-fibrous 60. %

JH-13	201101503-13	Yes	<1. %
-------	--------------	-----	-------

Location: Level 2, Northwest

Description: Grey, Homogeneous, Debris
 Asbestos Types: Chrysotile <1. %
 Other Material: Cellulose 10. %, Fibrous glass 40. %, Non-fibrous >49. %

JH-14	201101503-14		NA
-------	--------------	--	----

Location: Level 2, Southeast (VOID)

Description: Debris
 Asbestos Types:
 Other Material:

Comment: SAMPLE NOT SUBMITTED

Sent. By: HP LaserJet 3100;

5166820248;

Oct-10-01 8:47AM;

Page 8

OCT-09-2001 07:24

SCIENTIFIC LABS

212 679 9392 P. 09/12

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-0200 • FAX: (212) 679-0302

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nehlsen Date Examined 10/05/2001 P.O. # N1-3529
 1600 Rt. 22 East Page 4 of 8
 Union, NJ 07083

RE: N1-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/06/2001)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
JH-15	201101503-15	Yes	<1.5%
Location: Level 3, Southeast			
Description: Grey, Heterogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Material: Cellulose 10.5%, Fibrous glass 35.5%, Non-fibrous >54.5%			
JH-16	201101503-16	Yes	<1.5%
Location: Level 3, Southwest			
Description: Grey, Heterogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Material: Cellulose 10.5%, Fibrous glass 35.5%, Non-fibrous >54.5%			
JH-17	201101503-17	Yes	<1.5%
Location: Level 3, Center			
Description: Grey, Heterogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Material: Cellulose 10.5%, Fibrous glass 35.5%, Non-fibrous >54.5%			
JH-18	201101503-18	Yes	<1.5%
Location: Level 3, Northeast			
Description: Grey, Heterogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Material: Cellulose 3.5%, Fibrous glass 35.5%, Non-fibrous >61.5%			
JH-19	201101503-19	Yes	<1.5%
Location: Level 3, Northwest			
Description: Grey, Heterogeneous, Debris			
Asbestos Type: Chrysotile <1.5%			
Other Material: Cellulose 5.5%, Fibrous glass 30.5%, Non-fibrous >64.5%			

Sent By: HP LaserJet 3100;

5168820248;

Oct-10-01 8:47AM;

Page 7

OCT-09-2001 07:24

SCIENTIFIC LABS

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10018

TEL: (212) 679-8800 • FAX: (212) 679-8882

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nehlsen Date Examined 10/05/2001 P.O. # N1-3529
 1600 Rt. 22 East Page 5 of 8
 Union, NJ 07083

RE: N1-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/06/2001)

Client No. / BGA	Lab No.	Asbestos Present	Total % Asbestos
JH-20	201101503-20	Yes	<1. %
Location: Level 4, Southeast			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Materials: Cellulose 3. %, Fibrous glass 35. %, Non-fibrous >59. %			
JH-21	201101503-21	Yes	<1. %
Location: Level 4, Southwest			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Materials: Cellulose 3. %, Fibrous glass 40. %, Non-fibrous >56. %			
JH-22	201101503-22	Yes	<1. %
Location: Level 4, Center			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Materials: Cellulose 3. %, Fibrous glass 35. %, Non-fibrous >59. %			
JH-23	201101503-23	Yes	<1. %
Location: Level 4, Northwest			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Materials: Cellulose 3. %, Fibrous glass 30. %, Non-fibrous >64. %			
JH-24	201101503-24	Yes	<1. %
Location: Level 4, Northeast			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Materials: Cellulose 3. %, Fibrous glass 35. %, Non-fibrous >61. %			

Sent By: HP LaserJet 3100;

5166820246;

Oct-10-01 8:47AM;

Page 8

OCT-09-2001 07:24

SCIENTIFIC LABS

212 619 3396

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8800 • FAX: (212) 679-8899

PLM Bulk Asbestos Report

Hillman Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nehlsen Date Examined 10/05/2001 P.O. # N1-3529
 1600 Rt. 22 East
 Union, NJ 07083

Page 6 of 8

RE: N1-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/08/2001)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
JH-25	201101503-25	Yes	<1.5%
Location: Level 5, Northeast			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1.5%			
Other Materials: Cellulose 5.5%, Fibrous glass 30.5%, Non-fibrous >61.5%			
JH-26	201101503-26	Yes	<1.5%
Location: Level 5, Northwest			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1.5%			
Other Materials: Cellulose 5.5%, Fibrous glass 30.5%, Non-fibrous >64.5%			
JH-27	201101503-27	Yes	<1.5%
Location: Level 5, Southeast			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Materials: Cellulose 2.5%, Fibrous glass 30.5%, Non-fibrous 68.5%			
JH-28	201101503-28	Yes	<1.5%
Location: Level 5, Southwest			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Materials: Cellulose 2.5%, Fibrous glass 35.5%, Non-fibrous 61.5%			
JH-29	201101503-29	Yes	<1.5% 1.1.2
Location: Level 5, Center			
Description: Gray, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1.0%			
Other Materials: Fibrous glass 1.2%, Non-fibrous >95.5%			

Sent By: HP LaserJet 3100;

5166820246;

Oct-10-01 8:47AM;

Page 9

OCT-09-2001 07:24

SCIENTIFIC LABS

212 679 9392 P.09/14

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8800 • FAX: (212) 679-8888

PLM Bulk Asbestos Report

Hillman Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
 Attn: Mike Nielsen Date Examined 10/05/2001 P.O. # N1-3529
 1600 Rt. 22 East Page 7 of 8
 Union, NJ 07083

RE: N1-3529; ARCHON; 111 Washington Street / Parking
 Garage (AMENDED REPORT 10/06/2001)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
JH-30	201101503-30	Yes	<1.0%
Location: Roof, Southeast			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1.0%			
Other Materials: Cellulose 2.0%, Fibrous glass 40.0%, Non-fibrous >57.0%			
JH-31	201101503-31	Yes	<1.0%
Location: Roof, Southwest			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Traces			
Other Materials: Cellulose 1.0%, Fibrous glass 35.0%, Non-fibrous 64.0%			
JH-32	201101503-32	Yes	<1.0%
Location: Roof, Center			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Traces			
Other Materials: Cellulose 2.0%, Fibrous glass 35.0%, Non-fibrous 63.0%			
JH-33	201101503-33	Yes	<1.0%
Location: Roof, Northwest			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1.0%			
Other Materials: Cellulose 3.0%, Fibrous glass 35.0%, Non-fibrous >59.0%			

Reporting Notes:

- (1) Positive samples (<10%) analyzed by EPA Point Count Method (400 points).
- (2) PLM analysis of NDBs not essential.

Sent By: HP LaserJet 3100;

5188820248;

Oct-10-01 8:47AM;

Page 10/13

OCT-09-2001 07:25

SCIENTIFIC LABS

212 679 9392 P.07/12



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-6900 • FAX: (212) 679-6382

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/05/2001 SciLab Job No. 201101503
Attn: Mike Nehlsen Date Examined 10/05/2001 P.O. # N1-3529
1600 Rt. 22 East Page 8 of 8
Union, NJ 07083

RE: N1-3529; ARCHON; 111 Washington Street / Parking
Garage (AMENDED REPORT 10/06/2001)

(3) Composite analysis results for heterogeneous debris samples may be highly variable due to heterogeneity in materials present

Analyzed by: John Koubinda/Bella Chernis

*NAD/ND = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive step. PLM Bulk Asbestos Analysis by EPA 600/4-93-010 per 40 CFR 703 (NYLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYEDOH ELAP Lab # 11400). Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-fibrous organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 144, 38870, 8/1/96). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items listed. ARLA# 102843; VT Cont AL016855

Reviewed By: _____

Sent By: HP LaserJet 3100;

5166820246;

Oct-10-01 8:48AM;

Page 11/13

OCT-09-2001 07:25

SCIENTIFIC LABS

212 675 3334

FAX 212 675 3334

SAMPLE IDENTIFICATION FORM

Hillman Environmental Co., Inc.
1600 Route 23 B
Union, NJ 07083

*RUSIT***201101503**

CLIENT:

Archon

LOCATION:

*111 Washington St
Parking Garage*DATE: *10/5/01*JOB NO.: *111-1503*

NEED TYPED RESULTS BY: _____

Sample # Lab #	Floor:	Room:	Where in Room:	Sample of: Color of:	1
JH-01	1100		SOUTH CENTER	GRAY DEBRIS	
JH-02	"		CENTER	"	
JH-03	"		NORTH CENTER	"	
JH-04	1001		SOUTH EAST	"	
JH-05	"		SW	"	
JH-06	"		CENTER	"	
JH-07	"		NORTHWEST	"	
JH-08	"		NE	"	
JH-09	1002		SE	"	
JH-10	"		SW	"	
JH-11	"		CENTER	"	

SAMPLED BY:	CHAIN OF CUSTODY TRANSPORTED BY:	RECEIVED BY:	ANALYZED BY:
<i>Joe Hillman</i>		<i>W. Hillman</i>	
<i>10/5/01</i>		<i>10/5/01</i>	

Sent By: HP LaserJet 3100;

5166820248;

Oct-10-01 8:48AM;

Page 12/13

OCT-09-2001 07:25

SCIENTIFIC LABS

212 679 9392 P.11/12

SAMPLE IDENTIFICATION FORM

Hillman Environmental Co., Inc.
1600 Route 22 S
Union, NJ 07083

201101503

CLIENT: Amgen
LOCATION: 111 Chambers St
Ordering from

DATE: 10/5/01
JOB NO.: 101-1530
NEED TYPED RESULTS BY: _____

Sample # Lab #	Floor:	Room:	Where in Room:	Sample # Color of:	
JH-12	20112		NE	Gray Debris	
JH-13	"		NW	"	
JH-14	10113		SE VOID	—————	
JH-15	10113		SE	Gray Debris	
JH-16	"		SW	"	
JH-17	"		CENTER	"	
JH-18	"		NE	"	
JH-19	"	"	NW	"	
JH-20	10114		SE	"	
JH-21	"	"	SW	"	
JH-22	"		CENTER	"	

SAMPLED BY:	CHAIN OF CUSTODY TRANSPORTED BY:	RECEIVED BY:	ANALYZED BY:
John Hillman			
		<u>10/5/01</u>	
Date: <u>10/5/01</u>			

Sent By: HP LaserJet 3100;

5166820246 -> *: Page 13

Oct-10-01 8:48AM;

Page 13/13

OCT-09-2001 07:25

SCIENTIFIC LABS

SAMPLE IDENTIFICATION FORM

Hillman Environmental Co., Inc.
1600 Route 22 E
Union, NJ 07083

201101503

CLIENT: Argon
LOCATION: NY 10001

DATE: 10/5/01
JOB NO.: NY-1520
NEED TYPED RESULTS BY: _____

Pratt Green

Sample # Lab #	Floor:	Room:	Where in Room:	Sample of: Color of:
JH-23	1st/14		NW	Grey Brown
24	"		NE	"
25	1st/15		NE	"
26	"		SE NW	"
27	"		SE	"
28	"		SW	"
29	"		CENTER	"
30	Roof		SE	"
31	"		SW	"
32	"		CENTER	"
33	"		NW	"

SAMPLED BY:	CHAIN OF CUSTODY TRANSPORTED BY:	RECEIVED BY:	ANALYZED BY:
Jim Hillman		10/5/01	
		10/5/01	
		10/5/01	

TOTAL P. 12