

SciLab Job#: 202051557

Client Name: Applied Technology Services, Inc.

Table I
Summary of Bulk Asbestos Analysis Results
 E02411

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	26-050602-01 Roof, 16th Floor, SE Corner Roof Drains	DUS-001	---	---	---	---	NAD	NAD
02	26-050602-02 Roof, 16th Floor, 7th Column	DUS-001	---	---	---	---	NAD	NAD
03	26-050602-03 Roof, 16th Floor, Door A Right	DUS-001	---	---	---	---	NAD	NAD
04	26-050602-04 Roof, 16th Floor, Drain	DUS-001	---	---	---	---	NAD	NAD
05	26-050602-05 Roof, 16th Floor, Outer North Corner of Door A	DUS-001	---	---	---	---	NAD	NAD
06	26-050602-06 Roof, 16th Floor, 3rd Drain North	DUS-001	---	---	---	---	Chrysotile Trace	NA
07	26-050602-07 Roof, 16th Floor, Handrail 4th Column NS	DUS-001	---	---	---	---	Chrysotile Trace	NA
08	26-050602-08 Roof, 16th Floor, West Side of North Drain	DUS-001	---	---	---	---	Chrysotile Trace	NA
09	26-050602-09 Roof, 16th Floor, 2nd Handrail North	DUS-001	---	---	---	---	Chrysotile Trace	NA
10	26-050602-10 15th Floor, West Building Wall, Near Air Intake	ASH-001	---	---	---	---	NAD	NAD
11	26-050602-11 15th Floor, West Parapet Wall, 8' From South Corner	DUS-001	---	---	---	---	NAD	NAD
12	26-050602-12 15th Floor, West Side Air Intake, 6' From Roof Louver	WIP-001	---	---	---	---	NAD	NAD
13	26-050602-13 15th Floor, At North Side Drain	DEB-001	---	---	---	---	Chrysotile Trace	NA

See Reporting notes on last page

SciLab Job#: 202051557

Client Name: Applied Technology Services, Inc.

Page 2 of 2

Table I
Summary of Bulk Asbestos Analysis Results
 E02411

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
14	26-050602-14 East Side Walk, 10' South of Corner	DEB-002	----	----	----	----	Chrysotile Trace	NA
15	26-050602-15 15th Floor, East Side Walk, Window Leadge @Kitchen	ASH-002	----	----	----	----	Chrysotile Trace	NA
16	26-050602-16 15th Floor, South Side Walk, SE Corner, 6' West	ASH-003	----	----	----	----	Chrysotile Trace	NA

Analyzed by: Mikhail Gruzman  Date Analyzed 5/7/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogeneous materials).

Reviewed By: 