

LAB: Sci LAB

VIA: _____

240 NORTH AVENUE
NEW ROCHELLE NEW YORK 10801
(914) 654-0080 OR (914) 654-1332 FAX

EMPLOYEE NO: 26

BULK SAMPLE ANALYSIS

SAMPLE #	FLR # CODE	SAMPLE DISCRIPTION SPACE DESCRIPTION	SAMPLE LOCATION SAMPLE QUANTITY	TSM	ACM CODE	ASBESTOS	
						%	TYPE
26-050602-01	Roof 16	DUST COLLECTED @ DRAIN ROOF/16 FLOOR	SE CORNER ROOF DRAIN TWO FINGERS FULL	M	DUS-001		
26-050602-02	Roof 16	DUST + DEBRIS 7 HANDRAIL COLUMN ROOF/16 FLOOR	7 HANDRAIL COLUMN 1 CYLIND.	M			
26-050602-03	Roof 16	DUST IN MC OF DRAINAGE ROOF/16 FLOOR	DRAINAGE TO RIGHT OF AS MUCH AS I CAN SCRAPE	M			
26-050602-04	Roof 16	DUST + DEBRIS DRAIN @ REPAIRER ROOF	DRAIN @ FEET OF REPAIRER HANDFUL.	M			
26-050602-05	Roof 16	DUST SADDLE UNDER ROOF DOOR "A"	OUTER N. CORNR. OF DOOR "A" AS MUCH AS POSSIBLE.	M			
26-050602-06	Roof 16	DUST + DEBRIS ROOF/16 FLR	3 RD DRAIN NORTH TWO FINGERS FULL	M			
26-050602-07	Roof 16	DUST + DEBRIS ROOF HANDRAIL FTG.	1 ST HANDRAIL 4 TH COL. N-S FINGER FULL	M			
26-050602-08	Roof 16	DUST + DEBRIS ROOF/16 WESTERN EDGE	W. SIDE OF NORTH DRAIN HANDFULL	M			
26-050602-09	Roof 16	DUST + DEBRIS ROOF/16 WESTERN EDGE	2 ND HANDRAIL N	M	✓		

CHAIN- OF- CUSTODY

TURN-AROUND

RESULTS TO:

COMMENTS

SENT BY: <u>Chris McDuffie</u>	IMMEDIATE		
DATE: _____	6 HRS	FAX: _____	
RECEIVED BY: <u>elgdpurd</u>	12 HRS <u>X</u>	TEL: _____	
DATE: <u>5/6</u>	24 HRS	BEEPER: _____	
TIME: <u>1800</u>	72 HRS		

PUM, IF NEG TEM
QUAL-

202051557