

Applied Technology Services, Inc.**Bulk Sample Analysis Summary**

Location: 84 W. BROADWAY MANHATTAN NY
 ATS Project # A01200

Client:
 Client Reference #

SAMPLE ID #	FLR	APART ADDRESS	LOCATION	SAMPLE DESCRIPTION	TSM	ACM CODE	PLM TEM % TYPE	TEM AIRS	PCM AIRS
29-11-0501-01	P II	84 W. BROADWAY	W.B TOP OF SPEAKERS EAST SIDE	DUST WIPE	M	WIP-001	NVA		
29-11-0501-02		84 W. BROADWAY	BED COVER	DUST VACUUM	M	DVC-001	NVA		
29-11-0501-03		84 W. BROADWAY	G. BEDROOM BED SKIRT	DUST VACUUM	M	DVC-002	NVA		
29-11-0501-04		84 W. BROADWAY	M, BEDROOM	DUST WIPE	M	WIP-002	NVA		
29-11-0501-05		84 W. BROADWAY	BEDROOM BED COVER	DUST VACUUM	M	DVC-003	NVA		
29-11-0501-06		84 W. BROADWAY	BEDROOM WINDOW	DUST WIPE	M	WIP-003	NVA		
29-11-0501-07		84 W. BROADWAY	BEDROOM CLOTH-	DUST VACUUM	M	DVC-004	NVA		
29-11-0501-08		84 W. BROADWAY	LIVING ROOM QUILT ON WALL	DUST VACUUM	M	DVC-004	NVA		
29-11-0501-09		84 W. BROADWAY	OFFICE AREA W-WALL MILK CRATE	DUST WIPE	M	WIP-004	NVA		
29-11-0501-10		72 WARREN ST	LIVING ROOM CHAIR FRONT	DUST WIPE	M	WIP-005	NVA		
29-11-0501-11		72 WARREN ST	TOY BAG TOY WORM	DUST VACUUM	M	DVC-005	NVA		
29-11-0601-12		88 W.BROADWAY	BY ELEV. DOOR LIVING ROOM	DUST WIPE	M	WIP-006	NVA		
29-11-0601-13		88 W.BROADWAY	GOLD CHAIR BY WINDOW	DUST VACUUM	M	DVC-007	NVA		
29-11-0601-14		88 W.BROADWAY	WINDOW W.B.	DUST WIPE	M	WIP-007	NVA		
29-11-0601-15		88 W.BROADWAY	WINDOW W.B. SOFA COVER	DUST VACUUM	M	DVC-008	NVA		
29-11-0601-16		72 WARREN ST	R/S WALL PICTURE WARREN ST	DUST WIPE	M	WIP-008	NVA		

NAD = No Asbestos Detected
 PLM = Polarized Light Microscopy
 NVA = No Visible Asbestos
 NSD = No Structures Detected
 TEM Transmission Electron Microscopy
 NA = Not Analyzed

T = Thermal Systems Insulation
 S = Surfacing Materials
 M = Misc