

Applied Technology Services, Inc.

Bulk Sample Analysis Summary

Location: 84 W. BROADWAY MANHATTAN NY
 ATS Project # A01200

Client:
 Client Reference #

SAMPLE ID #	FLR	APART ADDRESS	LOCATION	SAMPLE DESCRIPTION	TSM	ACM CODE	PLM TEM % TYPE	TEM AIRS	PCM AIRS
29-11-0601-17	4 1/2	72 WARREN ST	SOFA MIDDLE OF	DUST VACUUM	M	DVC-009	NVA		
29-11-0601-18	3	88 W.BROADWAY	WINDOW SILL BEDROOM	DUST WIPE	M	WIP-009	NVA		
29-11-0601-19	3	88 W.BROADWAY	SOFA IN LIVING ROOM	DUST VACUUM	M	DVC-010	NVA		
29-11-0601-24	3	88 W.BROADWAY	SMALL CASSETTE PLAYER	DUST WIPE	M	WIP-010	NVA		
29-11-0601-20	3N	84 W. BROADWAY	WINDOW SILL W.B. SIDE	DUST WIPE	M	WIP-011	NVA		
29-11-0601-21	3N	84 W. BROADWAY	W.B. SOFA BY WINDOW	DUST VACUUM	M	DVC-011	NVA		
29-11-0601-22	2S	84 W. BROADWAY	KITCHEN WINDOW SILL R/S	DUST WIPE	M	WIP-012	Chrysotile PRESENT		
29-11-0601-23	2S	84 W. BROADWAY	LIGHT WOOD CHAIR LIVING ROOM	DUST VACUUM	M	DVC-012	Chrysotile PRESENT		
29-11-0601-25	3 1/2	72 WARREN ST	WINDOW SILL R/S	DUST WIPE	M	WIP-013	NVA		
29-11-0601-26	3 1/2	72 WARREN ST	SMALL BED IN BEDROOM	DUST VACUUM	M	DVC-013	NVA		
29-11-0601-27	4	74 WARREN ST	WINDOW SILL L/S	DUST WIPE	M	WIP-014	NVA		
29-11-0601-28	4	74 WARREN ST	PURPLE SOFA	DUST VACUUM	M	DVC-014	NVA		
29-11-0601-29	2	74 WARREN ST	R/S WINDOW SILL	DUST WIPE	M	WIP-015	Chrysotile PRESENT		
29-11-0601-30	2	74 WARREN ST	SOFA BY WINDOW	DUST VACUUM	M	DVC-015	Chrysotile PRESENT		
29-11-0601-31	5S	84 W. BROADWAY	W.B. L/S WINDOW SILL	DUST WIPE	M	WIP-016	NVA		

NAD = No Asbestos Detected
 PLM = Polarized Light Microscopy
 NVA = No Visible Asbestos
 NSD = No Structures Detected
 TEM = Transmission Electron Microscopy
 NA = Not Analyzed

T = Thermal Systems Insulation
 S = Surfacing Materials
 M = Misc