

**Applied Technology Services, Inc.****Bulk Sample Analysis Summary**

Location: 84 W. BROADWAY MANHATTAN NY  
 ATS Project # A01200

Client:  
 Client Reference #

| SAMPLE ID #   | FLR   | APART ADDRESS               | LOCATION                         | SAMPLE DESCRIPTION | TSM | ACM CODE | PLM TEM % TYPE | TEM AIRS                  | PCM AIRS |
|---------------|-------|-----------------------------|----------------------------------|--------------------|-----|----------|----------------|---------------------------|----------|
| 29-11-0601-32 | 5S    | 84 W. BROADWAY              | GREEN LEATHER FOOD STULL         | DUST VACUUM        | M   | DVC-016  | NVA            |                           |          |
| 29-110601-08  | 2S    | 84 W. BROADWAY              | LIVING ROOM                      | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-05  | 3S    | 84 W. BROADWAY              | LIVING ROOM                      | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-07  | 3N    | 84 W. BROADWAY              | LIVING ROOM                      | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-01  | 4N    | 84 W. BROADWAY              | S/W CORNER OF APARTMENT          | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-02  | 5N    | 84 W. BROADWAY              | MAIN BEDROOM                     | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-03  | 2     | 88 W. BROADWAY              | W.B SIDE BY WINDOW               | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-06  | 3     | 88 W. BROADWAY              | LIVING ROOM                      | AIR SAMPLES        |     |          |                | CHRYSTILE 1 FIBER PRESENT |          |
| 29-110601-09  | 3 1/2 | 88 W. BROADWAY              | MAIN BEDROOM                     | AIR SAMPLES        |     |          |                | CHRYSTILE 2 FIBER PRESENT |          |
| 29-110601-04  | 4     | 88 W. BROADWAY              | BY WINDOW OF MIDDLE OF THE APART | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-11  | 2     | 74 WARREN ST                | LIVING ROOM                      | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110601-10  | 4     | 74 WARREN ST                | BY POOL TABLE                    | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110701-19  | 1     | 82 W.B. GAME PARK           | BETWEEN STORE FL & OFFICE        | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110701-18  | 1     | 86 W.B. CIECK CASHING       | MIDDLE OF FLOOR                  | AIR SAMPLES        |     |          |                | NSD                       |          |
| 29-110701-16  | 1     | 88 W.B. ARCHITECTURE OFFICE | BY ENTRANCE TO OFFICE            | AIR SAMPLES        |     |          |                | NSD                       |          |

NAD = No Asbestos Detected  
 PLM = Polarized Light Microscopy  
 NVA = No Visible Asbestos  
 NSD = No Structures Detected  
 TEM Transmission Electron Microscopy  
 NA = Not Analyzed

T = Thermal Systems Insulation  
 S = Surfacing Materials  
 M = Misc