

Address: 41 MURRAY ST. AND 43 MURRAY

(SEPARATE BLDGS)

Bulk Samples PLM Yes No

Number of Negative ($\leq 1\%$) Samples _____

Number of Positive ($> 1\%$) Samples _____

Air Samples Yes No

PCM

Number of Samples Collected (≤ 0.01 f/cc) _____

Number of Samples Collected (>0.01 f/cc) _____

TEM *

Number of Samples Collected (≤ 70 s/mm²) _____

Number of Samples Collected (>70 s/mm²) _____

* WIDE SAMPLES IN STREET / SQ. CM - SEE ATT'Y RECORD

INDICATED THAT CLEANING DONE (RECORD TO FOLLOW)

pl.



666 Broadway
New York, NY 10012
Tel: (212) 529-5688
Fax: (212) 529-7987

FAX TRANSMITTAL SHEET

DATE: 2/22/02
TO: R. Radhakrishnan, P.E. - Director
COMPANY: DEP
FAX #: (718) 595-3744
FROM: Richard Kauke - Property Manager
BUILDING: 41 + 43 Murray Street
RE: Wipe Sample Results

BLDG CODE: 98

COMMENTS

Attached are the results of wipe samples performed at 41 + 43 Murray Street due to the WTC disaster. I am waiting for documentation of the clean up work that was performed at the above referenced building. He expects the report in the next few days. As soon as I receive the report I will fax to you. If you have any questions or require any additional information please feel free to call me at X274

NUMBER OF PAGES (INCLUDING COVER SHEET): 4

PLEASE ACKNOWLEDGE RECEIPT OF THIS FAX