WTC Visual Survey Form

Premise Address: 77 Murray St

Block: **Lot:**	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	**Name of Building:** NYC TRANSIT
# of Stories:	**AKA's:**	

Building Owner/Management:
Name: CARL Hallman
Telephone Number: ( )
FAX: ( )
Address:

On Site Contact:
Name: See Attached
Telephone Number: ( )

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____
Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Sample from from vents were negative.

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
Description: GRAVEL ROOF

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 8/16/2002 Inspection Team: Name: CARL + Plumpton Agency: DCS
Name: _____ Agency: _____

ENTERED

NYC 9/11 Public Portal Document

Brooklyn, NY 11201
Lawrence G. Reuter
President

Post-it® Fax Note 7671	Date 7.31.02	# of pages ▶ 1
To R. Radha Krishnan	From C. Hamann	
Co./Dept. NYC DEP	Co. NYCT	
Phone # ?	Phone # 718 243-8924	
Fax # 718 595-3744	Fax # 718 243-4357	

New York City Transit

July 31, 2002

Mr. R. Radhakrishnan, P.E.
Director, Asbestos Control Program
New York City Department of Environmental Protection
59-17 Junction Blvd.
Corona, NY 11638-5107

Re: 77 Murray Street

Dear Mr. Radhakrishnan:

This is to response to your July 19, 2002 letter requesting information regarding visible debris on the exterior of the New York City Transit (NYCT) building located at 77 Murray Street, New York, New York.

As stated in a letter to you, dated February 22, 2002, the substation was cleaned based on the September 12th bulk asbestos analytical results from ATC Associates. In response to your letter, NYCT performed a site inspection of the above-mentioned facility. While no visible debris was observed on the facade, there was a minute amount of debris on the roof level. The debris material was bulk sampled, sent to an accredited laboratory, analyzed for asbestos and found not to be asbestos containing.

NYCT believes that the minimal quantity of debris does not justify a clean-up effort. If the NYC DEP still wishes to conduct a cleaning of the exterior of the building or has any questions, please contact Carl Hamann, P.E., Manager, Hazard Abatement, at (718) 243-8924. Thank you.

PII

Sincerely,

James C. Wincek
Director, Hazard Assessment
Office of System Safety

cc: C. Hamann
C. Burrus
R. Stannish
E. Sacco

Spoke to Carl 8/5/02 ~ 9:15 am said will call back with time to inspect.

C:/CH/Asbestos/WTC-77Murray St

MTA New York City Transit is an agency of the Metropolitan Transportation Authority, State of New York
Peter S. Kalikow, Chairman

58-01-5512 0401

NYC-WTC_000097937

NYC-WTC_000097938

370 Jay Street
Brooklyn, NY 11201

New York City Transit



11373+3108 28

58-94-2002 6/95

NYC 9/11 Public Portal Document

NYC-WTC_000097939

370 Jay Street
Brooklyn, NY 11201

MTA **New York City Transit**

NYC 9/11 Public Portal Document

1137343108 28

58-94-2002 6/95

NYC-WTC_000097940

370 Jay Street
Brooklyn, NY 11201

Josephine Brown - Rm 819
New York City Transit



Mr. R. Radhakrishnan, P.E.
Director, Asbestos Control Program
NYC Dept. of Environmental Protection
59-17 Junction Blvd
Corona, New York 11638

11373+3108 28

58-94-2004

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

N.Y.C Transit Authority
77 Murray Street

Director
Mr. Charles Burrul

Environmental
Protection Industrial
Hygene
370 Jay Street
Bklyn, N.Y 11201

New York City
Department of
Environmental
Protection

59-17 Junction Blvd.
Corona, New York
11368
718•595•6565
718•595•3525 Fax

MARILYN GELBER
Commissioner

NYC 9/11 Public Portal Document

NYC-WTC_0000097942