

**ASBESTOS REMOVAL CORP.**

14-20 129th Street
College Point, New York 11356
(718) 961-4100 • Fax: (718) 961-4103

NYC DEP
PROJECT 44 NEW STREET
NEW YORK, NY

CONTRACT# ROF-REM3
INVOICE # 23
DATE 7/31/2002

ITEM#	DESCRIPTION OF ITEM	UNIT PRICE	TY/SQ. FT.	TOTAL VALUE
1	Roof cleanup-Asphalt/Uncovered Surface up to 2500 sq. ft. of clean-up per bldg/structure	\$ 1.00	0	\$ -
2	Roof cleanup-Asphalt/Uncovered Surface between 2500 sq. ft. 5000 sq. ft.	\$ 0.85	3000	\$2,550.00
3	Roof cleanup-Asphalt/Uncovered Surface greater than 5000 sq. ft.	\$ 0.80	0	\$ -
4	Roof cleanup-Gravel/Stone Surface up to 2500 sq. ft. of clean-up per bldg/structure	\$ 3.00	0	\$ -
5	Roof cleanup-Gravel/Stone Surface between 2500 sq. ft. and 5000 sq. ft.	\$ 2.75	0	0
6	Roof cleanup-Gravel/Stone Greater than 5000 Sq. FT.	\$ 2.50	0	0
7	Façade Clean-up (up to 5000 sq. ft.)	\$ 2.60	3050	\$ 7,930.00
8	Façade Clean-up (6-15 Story Buildings) (greater than 5000 sq. ft.)	\$ 2.45	0	\$ -
TOTAL				\$ 10,480.00

CHIEF ENGINEER

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
 Asbestos Control Program
 59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ONLY
 TYPEWRITTEN
 FORMS WILL BE
 ACCEPTED



ASBESTOS PROJECT NOTIFICATION
 (ASBESTOS INSPECTION REPORT)

Handwritten: Bu 0980Hw02
 Building Dept. or TRU No.
 FOR OFFICIAL USE ONLY
 1. *NYC DEP*
 (See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 44 New Street Borough Manhattan Zip 10004
 AKA _____ 3. Block 24 4. Lot _____
 5. Type of Facility _____ 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
 9. Tel. # _____ Fax # _____
 10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name Trio Asbestos Removal Corp. 13. Contact Person Chris Horan
 14. Federal Employer ID. # PII 15. Tel. # 718-961-4100 Fax # 718-961-4103
 16. Address 14-20 129th Street City College Point State NY Zip 11356

V. THIRD PARTY AIR MONITOR

17. Name Warren & Panzer Engineers, P.C. 18. Contact Person Michael Nolan
 19. Federal Employer ID. # _____ 20. Tel. # 212-922-0077 Fax # 212-922-0630
 21. Address 228 East 45th Street City New York State NY Zip 10017
 22. Sample Analysis Laboratory Warren & Panzer Engineers 23. NYS DOH ELAP # 11251

VI. PROJECT INFORMATION

24. Starting date for this portion of work 7/1/02 Projected completion date 7/31/02
 Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday
 Shift from: 8 ☒ am ☐ pm to 8 ☐ am ☒ pm
 If other, specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

6,050 Square Feet, and/or _____ Linear Feet



ACP 7
 2/2001

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler Asbestos Transportation Co. NYS DEC Permit # 1A-371 TEL # 631-924-5050

Disposal Site(s) Imperial/POB 47, 11 Boggs Rd., PA: Southern Alleghenies/Rd 3

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings) Valleyview Dr., PA

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☐ Clean up

29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT

TRN 09804402

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
Roof	Item No. 2	Roof and uncovered surfaces	3000	
Wall	Item No. 7	Partial Bulkhead & Parapet Walls	800	
Facade	Item No. 7	Partial West Facade	2250	

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

<u>Warren & Panzer</u> Print Name of Air Monitor <u><i>Baron C. C. C.</i></u> Signature <u>6/26/02</u> Date	<u>Trio Asbestos Rvl. Corp</u> Print Name of Asbestos Contractor <u><i>[Signature]</i></u> Signature <u>6/26/02</u> Date	<u>NYC</u> Print Name of Applicant (If other than Owner) <u><i>CL</i></u> Signature _____ Date
--	---	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

Carl R. H. H.
Print Name of Owner

[Signature]
Signature

Der
Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

ACP7
2/2001



AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P. C.
LABORATORY ID #: T02-07-037
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm²): 0.008643

PROJECT: NYC DEP, 44 New Street
DATE OF REPORT: 07/29/02
DATE OF ANALYSIS: 07/29/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (L)	G.O. % ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (struc./cm ³)	TOTAL ASBESTOS FILTER CONC. (str./mm ²)	AIR CONC. FOR STRUCT. 0.5 ≤ S ≤ 5 μm	AIR CONC. FOR STRUCT. S ≥ 5.0 μm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST TYPE SPECIFY
JB728 09	T02-07-037-1129	By Decon	1750	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB728 10	T02-07-037-1130	Left side	1750	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB728 11	T02-07-037-1131	Left Front	1750	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB728 12	T02-07-037-1132	Right Front	1750	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB728 13	T02-07-037-1133	Right side	1750	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA

ANALYST
E. Dimitrakas

LABORATORY DIRECTOR
Spiro Dangaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES Inc.) is a member of the American Society for Testing and Materials (ASTM).
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP as any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

228 East 45th Street
New York, NY 10017
(212) 922-8077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C. AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

P.O. _____

CLIENT: NYC DEP
PROJECT: 44 New st
LOCATION: Facade

W&P FILE #: 1079.01.22
LABORATORY: WKP
ANALYSIS METHOD: PCM TEM TEM
circle one 7400 AHERA EPA LEVEL II
TECHNICIAN: John Boyd

CONTACT: Mike Nolan

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (fib/cc.)
JB728 09	by Decen	3		5	5	0920	1510	350	1750	
JB728 10	Left side	3		5	5	0922	1512	350	1750	
JB728 11	Left Front	3		5	5	0924	1514	350	1750	
JB728 12	right Front	3		5	5	0926	1516	350	1750	
JB728 13	right side	3		5	5	0928	1518	350	1750	
JB728 14	Field Blank	1				0	0	0	0	
JB728 15	Blank	1				0	0	0	0	
JB728 16	Sealed Blank	1				0	0	0	0	

COMMENTS: 7-28-02

SAMPLE BY: John Boyd DATE: 7-28-02
SIGNATURE: [Signature]
RELEASED BY: John Boyd DATE: 7-28-02
SIGNATURE: [Signature]
RECEIVED BY: E. Sinyori DATE: 7/29/02
SIGNATURE: [Signature]

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION



AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P. C.
LABORATORY ID #: T02-07-032
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm^2): 0.008643

PROJECT: NYC DEP, 44 New
DATE OF REPORT: 07/28/02
DATE OF ANALYSIS: 07/28/02
EFFECTIVE FILTER AREA (mm^2): 385

LABORATORY RESULTS

CLIENT #	LAB ID #	LOCATION	VOLUME (ft)	G.O.'s ANALYZED	AREA ANALYZED (mm^2)	ANALYT. SENSITIVITY (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (struct./cm ²)	TOTAL ASBESTOS FILTER CONC. (str./mm ²)	AIR CONC. FOR STRUCT. 0.5µm-5µm	AIR CONC. FOR STRUCT. ≥5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
JB7270 2-01	T02-07-032-1104	Inside roof door	1755	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB7270 2-02	T02-07-032-1105	IWA north	1755	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB7270 2-03	T02607-032-1106	IWA south	1755	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB7270 2-04	T02-67-032-1107	IWA east	1755	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA
JB7270 2-05	T02-07-032-1108	IWA west	1755	6	0.0519	0.0042	<0.0042	<19.28	NA	NA	NA	NA

ANALYST
E. Sioukri

LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C. AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1

P.O. _____

CLIENT: NYC DEP
PROJECT: 44 New
LOCATION: Roof

W&P FILE #: 1079.01.02
LABORATORY: W&P
ANALYSIS METHOD: PCM TEM TEM
circle one 7400 NIHBA EPA LEVEL II
TECHNICIAN: John Boyd

CONTACT: Mike Nolan

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (fib/cc)
JA2702 01	Inside Roof door	3		9	9	1000	1315	195	1755	
JA2702 02	InH North	3		9	9	1022	1317	195	1755	
JA2702 03	InH South	3		9	9	1004	1314	195	1755	
JA2702 04	InH East	3		9	9	1006	1321	195	1755	
JA2702 05	InH West	3		9	9	1008	1323	195	1755	
JA2702 06	Field Blank	1		N/A	N/A	0	0	0	0	
JA2702 07	LI 11	1		N/A	N/A	0	0	0	0	
JA2702 08	Sealed Blank	1		N/A	N/A	0	0	0	0	

COMMENTS:

702-07-032

SAMPLE BY: John Boyd DATE: 7.27.02
SIGNATURE: John Boyd
RELEASED BY: John Boyd DATE: 7.27.02
SIGNATURE: John Boyd
RECEIVED BY: E. Spitzer DATE: 7/28/02
SIGNATURE: E. Spitzer

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT**

TOTAL FEET: 6050 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

**NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)**

TRU0980MN02

FEE EXEMPT: Yes

1. \$0.00

	F	SF	LF
roof	3,000	0	0
	0	0	0
wall	800	0	0
	0	0	0
faça	2,250	0	0
	0	0	0

START DATE: 7/1/02 COMPLETION DATE: 7/31/02

I. FACILITY

ADDRESS: 44 NEW STREET BORO: MANHATTAN ZIP: 10004
TYPE OFFACILITY: BLOCK: 24 LOT:

II. BUILDING OWNER

NAME: N/A
TEL. #:
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION
TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: 11-2869540
ADDRESS: 14-20 129 STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.
TEL. #: (212) 922-0077
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E
NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. RAMMOHAN SQUAD #: 1 BADGE #: A078

DATE OF INSPECTION: 7/27/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐

To: 8 AM ☐ PM ☒

Contact at site: Saba Simic, Handler Supervisor, John Boyd, Air Sampling Technician

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--------------------------------------|-----------------------------------|--|
| 1-51 - Notifications, Reports, Pla | 1-71 - Air Sampling and Monitorin | 1-91 - Worker Protection |
| 1-101 - Materials and Equipment | 1-116 - Work Place Preparation | 1-117 - Worker Decontamination System |
| 1-118 - Waste Decontamination System | 1-126 - Engineering Controls | 1-127 - Entry/Exit Procedures |
| 1-129 - Maintenance of Barriers | 1-138 - Encapsulation | 1-139 - Enclosure |
| 1-140 - Glovebag | 1-141 - Tent | 1-137 - ACM Disturbance, RemoveL, Handling |
| 1-146 - Preliminary Clean-up | 1-147 - Final Clean-up | |

Project not started Inspection

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: ☒ No ☒ Yes 1 2 3
4 5 6 Photos taken: ☒ Yes ☐ No

Additional comments: Six handlers started mobilizing to the roof and roof cleaning began. On street there were two vehicles parked in front of the building making it impossible to bring boom for facade cleaning. I contacted 1st pet and DOT and both pointed each other. Then I contacted Tom Deprisco of Mayor's office and left a message and no call back received. I then contacted Patrick Lanza of Mayor's office of operations at 10am and asked for help. Mr. Lanza said he will arrange for tow truck. 12:30 pm, 1st tow truck did not show up, and I contacted Krish, The ACP Director and briefed him. The crew completed the roofing clean-up at 6pm. The two cars parked were gone and the spot was secured with Trio's Truck and Horses for Dykes with Caution tapes for tomorrow's work.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

TOTAL FEET: 6050 0

ASBESTOS INSPECTION REPORT

Basis of Inspection:

TRU0980MN02

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTEDNOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

FEE EXEMPT: Yes

1. \$0.00

	SF	LF
roof	3,000	0
	0	0
	0	0
wall	800	0
	0	0
	0	0
faça	2,250	0
	0	0

START DATE: 7/1/02 COMPLETION DATE: 7/31/02

I. FACILITY

ADDRESS: 44 NEW STREET BORO: MANHATTAN ZIP: 10004
TYPE OFFACILITY: BLOCK: 24 LOT:

II. BUILDING OWNER

NAME: N/A
TEL. #:
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION
TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: 11-2869540
ADDRESS: 14-20 129 STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.
TEL. #: (212) 922-0077
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E
NYS ELAP #: 11251ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammohan SQUAD #: 1 BADGE #: A078

DATE OF INSPECTION: 7/28/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐To: 8 AM ☐ PM ☒

Contact at site: Sasa Simic, John Boyd, Steve Parmagiani.

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--------------------------------------|-----------------------------------|--|
| 1-51 - Notifications, Reports, Pla | 1-71 - Air Sampling and Monitorin | 1-91 - Worker Protection |
| 1-101 - Materials and Equipment | 1-116 - Work Place Preparation | 1-117 - Worker Decontamination System |
| 1-118 - Waste Decontamination System | 1-126 - Engineering Controls | 1-127 - Entry/Exit Procedures |
| 1-129 - Maintenance of Barriers | 1-138 - Encapsulation | 1-139 - Enclosure |
| 1-140 - Glovebag | 1-141 - Tent | 1-137 - ACM Disturbance, RemoveL, Handling |
| 1-146 - Preliminary Clean-up | 1-147 - Final Clean-up | |

Project not started

Inspection

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

☒ Project completed on or about 7/28/02 All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: ☒ No ☐ Yes 1 2 3
4 5 6 Photos taken: ☒ Yes ☐ No

Additional comments: The supervisor and four handlers set up dyke on the side walk to prepare for facade cleaning. The boom basket was plasticized and vacuuming started on facade ledges. Visual inspection of facade was conducted by me, Sasa Simic and John Boyd at 4:30 pm and additional cleanup required. The additional cleanup completed at 7pm. and crew cleaned the side walk and departed from location. Project completed

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS

BA