

26 BROADWAY
- cleaned -
8/2/02

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT

TOTAL FEET: 6050 0

TRU0980MN02

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

FEE EXEMPT: Yes
1. \$0.00

	1	2	3
roof	3,000	0	0
	0	0	0
wall	800	0	0
	0	0	0
face	2,250	0	0
	0	0	0

START DATE: 7/1/02 COMPLETION DATE: 7/31/02

I. FACILITY

ADDRESS: 44 NEW STREET BORO: MANHATTAN ZIP: 10004
TYPE OFFACILITY: BLOCK: 24 LOT:

II. BUILDING OWNER

NAME: N/A
TEL #: N/A
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION
TEL #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII
ADDRESS: 14-20 129 STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.
TEL #: (212) 922-0077
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E
NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. RAMMOHAN SQUAD #: 1 BADGE #: A078
DATE OF INSPECTION: 7/27/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐
To: 8 AM ☐ PM ☒

Contact at site: Sasa Simic, Handler Supervisor, John Boyd, Air sampling Technician.

Inspection disclosed that the following sections were complied with: (Check all that apply)

☐ 1-51 - Notifications, Reports, Pla	☐ 1-71 - Air Sampling and Monitorin	☐ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☐ 1-116 - Work Place Preparation	☐ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☐ 1-137 - ACM Disturbance, Removal, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	
☐ Project not started		Inspection

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: ☒ No ☒ Yes 1 2 3
4 5 6 Photos taken: ☒ Yes ☐ No

Additional comments: Six handlers started mobilizing to the roof and roof cleaning began. On street there were two vehicles parked in front of the building making it impossible to bring boom for facade cleaning. I contacted 1st pct and DOT and both pointed each other. Then I contacted Tom Deprisco of Mayor's office and left a message and no call back received. I then contacted Patrick Lanza of Mayor's office of operations at 10am and asked for help. Mr. Lanza said he will arrange for tow truck. 12:30 pm, 1st tow truck did not show up, and I contacted Krish, The ACP Director and briefed him. The crew completed the roofing clean-up at 6pm. The two cars parked were gone and the spt was secured with Trio's Truck and Horses for Dykes with Caution tape for tomorrow's work.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS
4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

2

SUPERVISOR INITIALS

W

**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT**

TOTAL FEET: 6050 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

**NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)**

TRU0980MN02

FEE EXEMPT: Yes
1. \$0.00

	SP	TV
roof	3,000	0
	0	0
	0	0
wall	800	0
	0	0
	0	0
faça	2,250	0
	0	0

START DATE: 7/1/02 COMPLETION DATE: 7/31/02

I. FACILITY

ADDRESS: 44 NEW STREET BORO: MANHATTAN ZIP: 10004
TYPE OFFACILITY: BLOCK: 24 LOT:

II. BUILDING OWNER

NAME: N/A
TEL. #:
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION
TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: **PII**
ADDRESS: 14-20 129 STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.
TEL. #: (212) 922-0077
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E
NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammohan SQUAD #: 1 BADGE #: A078
DATE OF INSPECTION: 7/28/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐
To: 8 AM ☐ PM ☒

Contact at site: Sasa Simic, John Boyd, Steve Parmagiani.

Inspection disclosed that the following sections were complied with: (Check all that apply)

☐ 1-51 - Notifications, Reports, Pla	☐ 1-71 - Air Sampling and Monitorin	☐ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☐ 1-116 - Work Place Preparation	☐ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☐ 1-137 - ACM Disturbance, Removal, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	
☐ Project not started . Inspection		
revealed all ACM to be intact. New start date: / /		
☐ Project ongoing, expected completion date: / /		
☒ Project completed on or about <u>7/28/02</u> All surfaces, including abated surfaces are free of visible ACM and encapsulat		
☐ Follow up necessary on / /		

Samples taken: ☒ No ☐ Yes 1 2 3
4 5 6 Photos taken: ☒ Yes ☐ No

Additional comments: The supervisor and four handlers set up dyke on the side walk to prepare for facade cleaning. The boom basket was plasticized and racking started on facade ledges. Visual inspection of facade was conducted by me, Sasa Simic and John Boyd at 4:30 pm and additional clean up required. The additional clean up completed at 7pm. and crew cleaned the side walk and departed from location. Project completed

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND
RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS
4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE
5
SUPERVISOR INITIALS
BL