

WTC Visual Survey Form

Premise Address: <u>44 NEW ST</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>6</u>	AKA's: <u>Boxing Gym</u>	
Building Owner/Management:		Telephone Number: ()
Name: <u>Cushman + Wakefield</u>		FAX: ()
Address:		
On Site Contact:		Telephone Number: (212) 425-1058
Name: <u>Mark Fergusson</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected		Debris			
North	☐ N/A	☐ Yes ☐ No		☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
South	☐ N/A	☒ Yes ☐ No		☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"	
East	☐ N/A	☐ Yes ☐ No		☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
West	☐ N/A	☒ Yes ☐ No		☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"	

Facade Description: _____

Roof

 Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"
 Description: _____
Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 6/17/2002
 Inspection Team: Name: CAPL
 Name: _____

 Agency: _____
 Agency: _____

ENTERED