




124 Nassau Street



WTC Visual Survey Form

BN#1001277

Premise Address: 124 Nassau Street		
Block: 92 Lot: 29	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
Facade Description: _____					

Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Roof has some visible debris</u>					

Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
<u>No access</u>					

Date: 2/19/2002

Inspection by: Name: CL

Agency: DEP

Name: _____

Agency: _____

Asbestos Inspection Report

Premise No. 124 NASSAU STREET					Inspection Date: AS NOTED	
Floor ROOF AND FACADE	Zip	Borough 1	Block 92	Lot 29	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
WEDNESDAY JUNE 26 2002						
8:00AM WORKERS BEGIN THE CLEANUPS OF THE ROOF AND SET BACK ROOF AREAS. FOR THE PURPOSES OF AIR MONITORING (SAMPLING), THE ROOF AREAS OF 118 NASSAU, 120 NASSAU, 122 NASSAU AND 124 NASSAU WILL BE TREATED AS ONE WORK AREA. A REMOTE DECON UNIT HAS BEEN ERECTED ON THE 3RD FLOOR OF 124 NASSAU STREET.						
FRIDAY JUNE 28 2002						
5:00PM WORKERS HAVE COMPLETED THE MAIN ROOF AND SET BACK ROOF AREA						
6:00PM I CONDUCT A VISUAL INSPECTION OF THE WORKAREAS AND FIND THAT THEY ARE FREE OF VISIBLE WTC DEBRIS.						
SUNDAY JUNE 30 2002						
8:00AM WORKERS BEGIN THE CONSTRUCTION OF A DYKE ON THE SIDEWALK TO COLLECT ANY WATER FROM THE SCHEDULED FACADE CLEAN-UPS OF 118 NASSAU, 120 NASSAU AND 124 NASSAU STREET. A DECON TRUCK WILL BE USED AS THE REMOTE DECON.						
6:00 PM I CONDUCT A VISUAL INSPECTION OF THE FACADE SURFACE AND FIND THAT IT IS FREE OF VISIBLE WTC DEBRIS. THE CLEAN-UP PROJECT FOR THIS PREMISE IS NOW COMPLETE. FOR THE PURPOSES OF AIR SAMPLING THE FACADES OF THE FOUR BUILDINGS WERE TREATED AS ONE WORK AREA.						

WTC Visual Survey Form

BN# 1001277

Premise Address: 124 NASSAU STREET		
Block: 92	Residential ☐ Commercial ☐	Name of Building:
Lot: 29	Mix Use ☐ Other ☐	PLUCK U. RESTAURANT
# of Stories: 4	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact: SEAN (REST. MGR)		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
Facade Description: DEBRIS FOUND ON ALL WINDOW LEDGES					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: ROOF HAS VISIBLE DEBRIS					
Setbacks N/A ☐					
Floor: 2ND		Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments BACKYARD (ACCESSIBLE FROM BSMT) HAS DEBRIS					

Date: 06 / 10 /2002

Inspection Team: Name: DA/A020
Name: _____Agency: NYC DEP
Agency: _____