

WTC Visual Survey Form

BN#1001275

Premise Address: 120 Nassau Street		
Block: 92	Residential ☐ Commercial ☐	Name of Building:
Lot: 27	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected ☐ Yes ☐ No	Debris ☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1" ☐ ½ to 1" ☐ > 1" ☐ ½ to 1" ☐ > 1" ☐ ½ to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	
East ☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	
West ☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	
Facade Description: _____			
Roof			
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"			
Description: <u>Some debris visible on roof</u>			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			
<u>No Access</u>			

Date: 2/19/2002

Inspection by: Name: CL

Agency: DEP

Asbestos Inspection Report

Premise No. 120 NASSAU STREET					Inspection Date: AS NOTED	
Floor ROOF AND FACADE	Zip	Borough 1	Block 92	Lot 27	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip NY 11236		Phone (718)531-2900		Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York		Address City				
State Zip NY 10017		Phone (212) 922-0077		State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
WEDNESDAY JUNE 26 2002						
8:00AM WORKERS BEGIN THE CLEANUPS OF THE ROOF AND SET BACK ROOF AREAS. FOR THE PURPOSES OF AIR MONITORING (SAMPLING), THE ROOF AREAS OF 118 NASSAU, 120 NASSAU, 122 NASSAU AND 124 NASSAU WILL BE TREATED AS ONE WORK AREA. A REMOTE DECON UNIT HAS BEEN ERECTED ON THE 3RD FLOOR OF 124 NASSAU STREET.						
FRIDAY JUNE 28 2002						
5:00PM WORKERS HAVE COMPLETED THE MAIN ROOF AND SET BACK ROOF AREA						
6:00PM I CONDUCT A VISUAL INSPECTION OF THE WORKAREAS AND FIND THAT THEY ARE FREE OF VISIBLE WTC DEBRIS.						
SUNDAY JUNE 30 2002						
8:00AM WORKERS BEGIN THE CONSTRUCTION OF A DYKE ON THE SIDEWALK TO COLLECT ANY WATER FROM THE SCHEDULED FACADE CLEANUPS OF 118 NASSAU, 120 NASSAU AND 124 NASSAU STREET. A DECON TRUCK WILL BE USED AS THE REMOTE DECON.						
6:00 PM I CONDUCT A VISUAL INSPECTION OF THE FACADE SURFACE AND FIND THAT IT IS FREE OF VISIBLE WTC DEBRIS. THE CLEAN-UP PROJECT FOR THIS PREMISE IS NOW COMPLETE. FOR THE PURPOSES OF AIR SAMPLING THE FACADES OF THE FOUR BUILDINGS WERE TREATED AS ONE WORK AREA.						