

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306



Attn: Mr. Fabio Pedone
 Warren & Panzer Engineers, P.C.
 228 E. 45th Street
 New York NY 10017

Received: 6/14/02 9:00:00 PM
 ATC Group #: 8111
 Analysis Date: 6/15/02

Fax: (212) 922-0630 Phone: (212) 922-0077

Project: NYC-DEP W & P File #: 1079.01.02
 116

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
 by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non-Asb	Asbestos Type(s)	# Structures 0.5µ-5 µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²)	(S/cc)	Notes
03 8111 -1	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
04 8111 -2	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
05 8111 -3	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
06 8111 -4	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
07 8111 -5	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048

MARK PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10875

228 East 45th Street
New York, NY 10017
(212) 922-0877
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a P.O.

PAGE 1 OF 1

CLIENT: N.Y.C.D.P.E.P.

PROJECT: 116 NASSAU ST. N.Y.C.

LOCATION: Low Level Range & WHE

W&P FILE #: 1079-01-02

LABORATORY: ATC ENV.

ANALYSIS METHOD: PCM

circle one 7400

TECHNICIAN: Lawrence Boer

CONTACT: MIKE NOVA

LLWH: _____

SCA JOB#: _____

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
-01	FIELD BLANK	1	—	—	—	1001	—	—	—	—
-02	FIELD BLANK	1	—	—	—	1002	—	—	—	—
-03	CLEAN ROOM REVERSE DRAIN	3	04	3.0	3.0	1005	1805	480	1490	—
-04	PAT-LOW ROOF EAST	3	07	3.0	3.0	1006	1806	480	1490	—
-05	APT - MED-ROOF EAST	3	14	3.0	3.0	1009	1809	480	1490	—
-06	APT - INSIDE WEST	3	11	3.0	3.0	1012	1812	480	1490	—
-07	APT - INSIDE EAST	3	22	3.0	3.0	1013	1813	480	1490	—
-08	CAPPED BLANK	1	—	—	—	—	—	—	—	—

COMMENTS:

* PLEASE FOR RESULTS TO W&P ENV, P.C

SAMPLE BY: LAWRENCE BOER	DATE: 6/14/02
SIGNATURE: Lawrence Boer	DATE: _____
RELEASED BY: LAWRENCE BOER	DATE: _____
SIGNATURE: Lawrence Boer	DATE: _____
RECEIVED BY: M. Boer	DATE: 06/19/02
SIGNATURE: _____	DATE: _____

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INSTRUCTIONS