

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306



Attn: Mr. Fabio Pedone
Warren & Panzer Engineers, P.C.
228 E. 45th Street
New York NY 10017

Received: 6/19/02 9:00:00 PM
ATC Group #: 8183
Analysis Date: 6/20/02

Fax: (212) 922-0630 Phone: (212) 922-0077

Project: NYC-DEP W & P File #: 1079.01.02
116 Nassau Street, New York, NY

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5 µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²) (S/cc)	Notes
03 8183 -1	1800.00	0.0450	0	CHRYSTILE	1 0	0.0048	22.24 0.0048	
04 8183 -2	1800.00	0.1349	0	CHRYSTILE	1 2	0.0048	66.73 0.0143	
05 8183 -3	1800.00	0.0899	0	CHRYSTILE	2 0	0.0048	44.43 0.0095	
06 8183 -4	1800.00	0.0450	0	None Detected	0 0	0.0048	<22.24 <0.0048	
07 8183 -5	1800.00	0.0450	0	CHRYSTILE	1 0	0.0048	22.24 0.0048	

ROMAN PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

**2225 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 6

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate⁺/a

ॐ

W&P FILE #: 1079-01-02

CLIENT: N.Y.C. D.E.P.

LABORATORY: ATC Corp.

PROJECT: 116 NASSAU ST. NYC, N.Y.

ANALYSIS METHOD: PCM TEM TEM

LOCATION: East side of West Lake, Casavades
Ranch

circle one 7400 ANHERA EPA LEVIN

TECHNICIAN: LAWRENCE BAKER

TECHNICIAN: LAWRENCE BAKER

TECHNICIAN: LAWRENCE BAKER

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
-01	FRESH BLACK	1	—	— —	0805 —	—	—	—
-02	FRESH BLACK	1	—	— —	0806 —	—	—	—
-03	CLEAR RUN BELOW (PENALTY)	3	06	2.0 3.0	0807 1809	600	1800	—
-04	MID ROOF ANT-COAGULATED SOLIDS	3	11	3.0 3.0	0812 1812	600	1800	—
-05	MID ROOF ANT-COAGULATED SOLIDS	3	14	3.0 3.0	0814 1814	600	1800	—
-06	INSIDE 3RD FL. ANT-COAGULATED ROOF	3	21	3.0 3.0	0815 1815	600	1800	—
-07	INSIDE 3RD FL. ANT-MID ROOF	3	08	3.0 3.0	0817 1817	600	1800	—
-08	CAPPER BLACK	1	—	— —	— —	—	—	—

COMMENTS:

#3/83

SAMPLE BY: CHARLIE BAKER DATE: 6/19/02

DATE: 6/19/02

SIGNATURE: Lucy Bar WARDENSDALE

Personen

RELEASED BY: *Lawrence Board* DATE: *Jan 11*

DATE: _____

SIGNATURE: Sam Bae

1

RECEIVED BY: Mr. Lab T. G. Kocak DATE: 06/19/92

DATE: 06/19/0

RECEIVED BY: _____
 SIGNATURE: _____

2011/01/24

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION