

Asbestos Inspection Report

Premise No. 86 1/2 NASSAU STREET					Inspection Date: AS NOTED	
Floor ROOF AND FACADE	Zip 10038	Borough 1	Block 78	Lot	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken <u>Yes</u> /No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name HON. EDWARD FINCH		
Address City 228 East 45 Street New York				Address City PII		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone NY 10021 PII		
Contact Person				Time of Inspection from: AS NOTED		
SUNDAY JULY 14, 2002						
1:00AM WORKERS BEGIN THE CONSTRUCTION OF A DYKE TO COLLECT WATER FROM FACADE CLEAN-UPS. THE FACADE CLEAN UP OF 86, 86 1/2, AND 88 NASSAU STREET WILL OCCUR SIMULTANEOUSLY AND WILL BE TREATED AS ONE WORK AREA FOR THE PURPOSES OF AIR MONITORING.						
9:00AM DYKE HAS BEEN CONSTRUCTED. A MOBILE DECON TRUCK WILL BE USED.						
10:30AM WORKERS BEGIN VACUUMING BULK MATERIAL FROM THE FACADE. FESTY OSEMWEGIE OF WARREN AND PANZER BEGINS AIR SAMPLING. FIVE AIR SAMPLES WILL BE RUN.						
12:00 PM VACUUMING COMPLETED. WORKERS BREAK FOR LUNCH.						
12:45 PM WASHING OF FACADES BEGINS						
4:00PM WASHING OF FACADES COMPLETED						
4:00-5:00PM I CONDUCT A VISUAL INSPECTION OF THE CLEANED FACADES AND OBSERVE NO VISIBLE WTC DEBRIS						
5:10 PM WORKERS DISMANTLE DYKE						
6:00PM WORKERS LEAVE THE WORK SITE.						
MONDAY JULY 15, 2002						
8:00AM WORKERS BEGIN CLEAN UP ACTIVITIES ON THE ROOF. AIR SAMPLING WILL BE CONDUCTED BY FESTY OSEMWEGIE OF WARREN & PANZER ENGINEERS. AIR SAMPLING PUMPS LOCATED ON THE ROOF OF THE ADJACENT BUILDING (122 EATON STREET).						
2:00PM WORKERS COMPLETE THE ROOF CLEAN UP AND BREAK FOR LUNCH. A VISUAL INSPECTION WILL BE CONDUCTED WHEN THE WORK AREA IS DRY.						
4:00PM I CONDUCT A VISUAL INSPECTION OF THE WORK AREA AND OBSERVE NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.						

Asbestos Inspection Report

Premise No. 86 1/2 NASSAU STREET					Inspection Date: AS NOTED	
Floor ROOF AND FACADE	Zip 10038	Borough 1	Block 78	Lot	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken <u>Yes</u> /No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name HON. EDWARD FINCH		
Address City 228 East 45 Street New York				Address City PII		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone NY 10021 PII		
Contact Person				Time of Inspection from: AS NOTED		
SUNDAY JULY 14, 2002						
1:00AM WORKERS BEGIN THE CONSTRUCTION OF A DYKE TO COLLECT WATER FROM FACADE CLEAN-UPS. THE FACADE CLEAN UP OF 86, 86 1/2, AND 88 NASSAU STREET WILL OCCUR SIMULTANEOUSLY AND WILL BE TREATED AS ONE WORK AREA FOR THE PURPOSES OF AIR MONITORING.						
9:00AM DYKE HAS BEEN CONSTRUCTED. A MOBILE DECON TRUCK WILL BE USED.						
10:30AM WORKERS BEGIN VACUUMING BUILD MATERIAL FROM THE FACADE. FESTY OSEMWEGIE OF WARREN AND PANZER BEGINS AIR SAMPLING. FIVE AIR SAMPLES WILL BE RUN.						
12:00 PM VACUUMING COMPLETED. WORKERS BREAK FOR LUNCH.						
12:45 PM WASHING OF FACADES BEGINS						
4:00PM WASHING OF FACADES COMPLETED						
4:00-5:00PM I CONDUCT A VISUAL INSPECTION OF THE CLEANED FACADES AND OBSERVE NO VISIBLE WTC DEBRIS						
5:10 PM WORKERS DISMANTLE DYKE						
6:00PM WORKERS LEAVE THE WORK SITE.						
MONDAY JULY 15, 2002						
8:00AM WORKERS BEGIN CLEAN UP ACTIVITIES ON THE ROOF. AIR SAMPLING WILL BE CONDUCTED BY FESTY OSEMWEGIE OF WARREN & PANZER ENGINEERS. AIR SAMPLING PUMPS LOCATED ON THE ROOF OF THE ADJACENT BUILDING (122 HANSON STREET).						
2:00PM WORKERS COMPLETE THE ROOF CLEAN UP AND BREAK FOR LUNCH. A VISUAL INSPECTION WILL BE CONDUCTED WHEN THE WORK AREA IS DRY.						
4:00PM I CONDUCT A VISUAL INSPECTION OF THE WORK AREA AND OBSERVE NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.						