WTC Visual Survey Form

1001257

Premise Address: 111 NASSAU ST.

Block: 90 **Lot:** 18 | Residential ☐ Commercial ☐ Mix Use ☐ Other ☐ _____ | **Name of Building:**

# of Stories: | **AKA's:**

Building Owner/Management:
Name: | Telephone Number: ( ) FAX: ( )

Address:

On Site Contact:
Name: Pilades Optical | Telephone Number: (212) 227-9895

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: AWNINGS - DEBRIS OBS. @ AWNINGS

Roof

Debris: ☐ No Visible /Fine Layer ☒ to 1" ☐ > 1"
Description: _____

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 2/19/2002 ✓ Inspection by: Name: C.L. Agency: DEP
Name: _____ Agency: _____