

FROM : ABCO Exterior Rest

FAX NO. : 8457272068

Dec. 06 2002 06:25PM P2

Preventive Maintenance Inspections, Inc.

318 East 70th Street
New York, NY 10021

Cell
Fax

(732) 643-8905
(212) 327-4500
(914) 772-6094
732) 643-1057

December 6, 2002

NYC DEP
59-17 Junction Boulevard,
Flushing, New York, 11373-5108

Attention: Penny Theodorellis

Re: 93 Nassau Street.
135-139 Fulton Street,
28-34 Ann Street, New York, New York


Dear Ms. Theodorellis,

Regarding our conversation of December 6, pertaining to the collection of samples at 93 Nassau Street AKA 135-139 Fulton Street, 28-34 Ann Street, New York, New York. I personally collected the samples on the 3rd of September the following is a list of procedures:

1. Samples were collected from outside the window of room 312. This was the north window facing east on the Nassau Street side of the building.
2. Samples were collected at approximately 3:30 PM on 09/03/2002.
3. First sample collected was from the windowsill, the sample was collected using a sterile plastic spoon. The sample was placed into a marked new ziploc bag.
4. Second sample was a large paint chip collected from the north side of the exterior cast iron window casing. This sample was collected using a tweezers and placed into a marked ziploc bag. This sample was tested only on the front painted side.
5. The third sample was collected from the south window casing of the same window it was a smaller chip, which was blackened on the backside. This sample was collected with a tweezers and placed into a marked ziploc bag. This chip was only tested on the blackened side. The blackened side which was dislodged from the cast iron.
6. All the samples were then placed individually into a crash proof tube and placed into a box holding a bed of Styrofoam chips to ensure unbroken delivery to the testing laboratory.
7. The package was sent by Federal Express to the Ambient Group Inc. 10 Morris Avenue, Glen Cove, New York 11542.
8. The package was received on 09/04/2002 and assigned a job number C/S-4033 It was analyzed on 09/05/2002.

If you have any questions regarding the testing and collection of samples please contact me anytime at 914-772-6094.

Very truly yours,



MAURICE SCHICKLER
President



AMBIENT GROUP, INC.

10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-9009 • Fax: (516) 609-6271

Laboratory Report

AGL04033

Dust Characterization Laboratory Data Report

Client: Preventive Maintenance Inspection, Inc
Address: 318 East 70th Street
New York, NY 10021
Collected By: Client Submitted
Collected: 09/03/2002

Job Number: C/S-4033
Date Received: 09/04/2002
Date Analyzed: 09/05/2002
Job Location: 139 Fulton Street

Lab ID Field ID	Sample Location	Constituents	Percent of Sample **
0004033-001	Dust from World Trade Center	Carbon Particles	10
		Cellulose	20
		Cement Dust	30
		Chrysotile	15
		Fiber Glass	30
		Gravel Road Dust	8.5
			100
0004033-002	Large Paint Chip	Carbon Particles	10
		Cellulose	15
		Cement Dust	20
		Fiber Glass	40
		Gravel Road Dust	15
			100
0004033-003	Smaller Paint Chip, Blacken Side	Carbon Particles	20
		Cellulose	10
		Cement Dust	20
		Fiber Glass	5
		Gravel Road Dust	35
		Rust	10
			100

Tarek Fata

SIGNED FOR AMBIENT GROUP, INC. BY:

FROM : ABCD Exterior Rest

FAX NO. : 8457272068

Dec. 06 2002 06:24PM P1

Preventive Maintenance Inspections, Inc.

318 East 70th Street
New York, NY 10021

(212)327-4500
fax No. (732)643-1057
cell #914-7726094

FAX COVER SHEET

DATE: December 6, 2002
TO: D.E. P
ATTENTION: PENNY THEODORELLYS
FAX NO.: 718-595-3744
FROM: Maurice Schickler
SUBJECT: Re:93 Nassau St.,
135-139 Fulton St.,
28-34 Ann St.

NUMBER OF PAGES, INCLUDING COVER: 3