

WTC Visual Survey Form

Premise Address: <u>59 Warren St</u>		
Block:	Residential ☒ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: <u>Re - Inspect</u>		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Rear window ledges not touched</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 5/16 /2002Inspection Team: Name: CAVE

Agency: _____

Name: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>57 Murray St</u>		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building: <u>ROAD House</u>
# of Stories: <u>3</u>	AKA's:	
Building Owner/Management Name:		Telephone Number: (212) 619 4633 FAX: (cell) 914 263-4307
Address:		
On Site Contact Name: <u>HONG</u>		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected ☒ Yes ☐ No ☒ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		Debris ☐ No Visible/Fine Layer ☒ No Visible/Fine Layer ☐ No Visible/Fine Layer ☐ No Visible/Fine Layer		☐ ½ to 1" ☐ ½ to 1" ☐ ½ to 1" ☐ ½ to 1"
					☒ > 1" ☐ > 1" ☐ > 1" ☐ > 1"
Facade Description: <u>Rept facade not touched ↑ debris on ledges</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Debris on AC units, Pockets of debris in various locations</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Comments					

Date: 5/16/2002Inspection Team: Name: CARLAgency: _____
Agency: _____

WTC Visual Survey Form

Premise Address: <u>59 Murray St.</u>		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building: <u>NY DOLLS !!</u>
# of Stories:	AKA's:	
Building Owner/Management Name:		Telephone Number: () FAX: ()
Address:		
On Site Contact Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected ☒ Yes ☐ No ☒ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		Debris ☐ No Visible/Fine Layer ☒ No Visible/Fine Layer ☐ No Visible/Fine Layer ☐ No Visible/Fine Layer		☐ ½ to 1" ☐ ½ to 1" ☐ ½ to 1" ☐ ½ to 1"
					☒ > 1" ☐ > 1" ☐ > 1" ☐ > 1"
Facade Description: <u>Rear ledges not cleaned</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Pockets of debris, 3 large black garbage bags on roof, debris around bags</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 5/16 2002Inspection Team: Name: CARLAgency: _____
Agency: _____

WTC Visual Survey Form

Premise Address: <u>61 Warren St</u>		
Block:	Residential ☒ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>6</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Re-inspection.

Visual Inspection Results:

Facade:

		Inspected	Debris	Debris	Debris	Debris
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"	
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Facade Description: <u>Rear ledges not touched</u>						

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"

Comments

Date: 5/16/2002Inspection Team: Name: CARL

Name: _____

Agency: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>61-75 West Broadway</u>			
Block:	Residential ☒ Commercial ☒	Name of Building:	
Lot:	Mix Use ☐ Other ☐		
# of Stories: <u>6</u>	AKA's:		
Building Owner/Management:		Telephone Number: ()	
Name:		FAX: ()	
Address:			
On Site Contact:			
Name:		Telephone Number: ()	
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No Locations: <u>Re-inspect</u>			
ACM Clean Up ☐ Yes ☐ No Locations:			
Air Monitoring ☐ Yes ☐ No Locations:			
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:			
North	☐ N/A	Inspected	Debris
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
Facade Description: <u>Window ledges dirty on East side</u> <u>not touched</u>			
Roof			
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"			
Description: <u>Small pockets present, debris observed</u> <u>around hatches.</u>			
Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Comments			

Date: 5/16/2002Inspection Team: Name: CARL
Name: _____Agency: _____
Agency: _____

S9 MURRAY

1082029

WTC Visual Survey Form

(9)

Premise Address: <i>61 Warren St / 73 W Broadway</i>	
Block: ████	Residential ☐ Commercial ☒
Lot: ████	Mix Use ☐ Other ☐
# of Stories:	AKA's: ██
Building Owner/Management: Name:	Telephone Number: () FAX: ()
Address:	
On Site Contact: Name:	
Telephone Number: ()	
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____	
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <i>Broken windows etc... Facade still dirty</i>					
Roof					
Debris: ☐ No Visible /Fine Layer <i>light dust</i> ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: <i>No Access to roof</i>					
Setbacks <i>N/A</i> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 3/5 /2002Inspection Team: Name: ALAgency: _____
Agency: _____

WTC Visual Survey Form

Premise Address: <u>59 Murray St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 8/28/2002Inspection Team: Name: AL

Agency: _____

Name: _____

Agency: _____

ENTERED