

WTC Visual Survey Form

Premise Address: <u>83 Murray</u>		
Block:	Residential ☒ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
Lot:		
# of Stories: <u>6</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>STREET INSPECTION</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>POCKETS UNDER EQUIPMENT INSPECTED FROM 81 Murray</u>					
Setbacks N/A ☒					
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments					

Date: 01/26 /2002Inspection Team: Name: AL
Name: LINERICKAgency: _____
Agency: _____

A2, H 3