

WTC Visual Survey Form

1001106

Premise Address: <u>65 Wallman St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
		Inspected	Debris
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description: <u>Brick windows etc facades and windows are still</u> <u>dirty</u>			
Roof			
Debris: ☐ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.			
Description: _____			
Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			
<u>NO Access to inspect the roof.</u>			

Date: 3/12/2002

Inspection Team: Name: AL

Agency: _____
Name: _____