

**BENJAMIN KURZBAN
& SON CONTROL, INC.**
1248 Ralph Ave.
BROOKLYN, N.Y. 11236

(718) 531-2900

TO
Dept of Environmental Protection
59-17 Junction Blvd
Corona, NY 11368

INVOICE

1183

DATE 9/11/02	ORDER NO.
SHIP TO Contract ROF-REM2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS
QUANTITY	DESCRIPTION	UNIT PRICE	TOTAL	
>	Registration # CT 82620020015280 Pin# 82602WTCROOF2			
	For work completed at 101 Maiden Lane 27,433 SF @ 2/SF			
	Total Amount due this Invoice		\$54,866.00	
	<i>R. Katz</i>			

ORIGINAL

STW

Thank You!

24

22. Sample Analysis Laboratory _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 09/03/02 Projected completion date 09/10/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday

Shift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item

25. Total amount of asbestos-containing material to be abated during this work

21433 Square Feet, and/or 0 Linear Feet



ACP
2/20

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

TRU 1401M402
Building Dept. or TRU No
FOR OFFICIAL USE ONLY
1. NYC DEP
(See fee schedule)

ONLY
TYPE WRITING
FORMS MAY BE
USED



EMERGENCY

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 101 MAIDEN LANE Borough MAN Zip 10038
AKA _____ 3. Block 68 4. Lot 10
5. Type of Facility MIXED USE 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
9. Tel. # _____ Fax # _____
10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL INC. 13. Contact Person LOUIE IANNICO
14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # PII 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 09/03/02 Projected completion date 09/03/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pm

If other, specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

21433 Square Feet, and/or 0 Linear Feet



ACP
2/200

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler IESI, NY NYS DEC Permit # NJ 462 Tel.# (718) 522-2263
 Disposal Site(s) BLUE RIDGE LANDFILL P.O. BOX 399 SCOTSDALE PA 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up



29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT ROOF MATERIAL: ROOF MEMBRANE (TAB)

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
ROOF	BULK HEADS	ROOF & WALL SURFACES	1367	
"	PARAPET WALL	WALL SURFACES	1016	
"		ROOF SURFACE	3636	
"		METAL SURFACES	300	
2ND FL	SET BACK	ROOF SURFACE	300	
FACADE	NORTH	FACADE SURFACES	2100	
"	EAST (PEARL ST)	WINDOWS & LEDGES	2186	
"	WEST	FACADE SURFACES	2625	
"	INTERIOR	FACADE SURFACES	2185	
"	SOUTH (MAIDEN LANE)	FACADE SURFACES	11718	INCLUDES AWNINGS & STORE FRONTS

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor  Signature 08-15-02 Date	B. KUEBBAN & SON CONTROL INC Print Name of Asbestos Contractor  Signature 08-15-02 Date	_____ Print Name of Applicant (if other than Owner) _____ Signature _____ Date
---	--	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

 Print Name of Owner

 Signature

 Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

09/09/2002 21:33 FAX 718 784 4065

003

**ATHENICA**

ENVIRONMENTAL SERVICES INC.

TEL (718) 784-7490
FAX (718) 784-4065**AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**

CLIENT: Warren & Panzer Engineers, P.C.
 LABORATORY ID #: T02-09-020
 ANALYT. METHODOLOGY: AHERA
 FILTER TYPE: MCEB
 AVERAGE G.O. AREA (mm²): 0.013771

PROJECT: NYC DEP, 101 Maiden Lane
 DATE OF REPORT: 09/08/02
 DATE OF ANALYSIS: 09/08/02
 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB ID	LOCATION	VOLUME (L)	G.O. ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITV. (street/cm ²)	TOTAL ASBESTOS AIR CONC. (street/cm ²)	TOTAL ASBESTOS FILTER CONC. (street/cm ²)	AIR CONC. FOR STRUCT. 0.5-5.0µm	AIR CONC. FOR STRUCT. >5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-09-020-2164	On Pearl St. left side	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
02	T02-09-020-2165	On Pearl St. right side	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
03	T02-09-020-2166	On Maiden Lane left side	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
04	T02-09-020-2167	On Maiden Lane center	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
05	T02-09-020-2168	On Maiden Lane right side	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA

ANALYST
L. GIOVANNILABORATORY DIRECTOR
Spiro Doweatis

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- This report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athena Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

SEE REVERSE SIDE FOR ANALYSIS INFORMATION


ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel: (718) 784-7490

Fax: (718) 784-4085

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.

PROJECT: NYC DBP, 101 Maiden Lane

LABORATORY ID #: T02-09-024

DATE OF REPORT: 09/08/02

ANALYT. METHODOLOGY: AHERA

DATE OF ANALYSIS: 09/08/02

FILTER TYPE: M.C.F.

 EFFECTIVE FILTER AREA (mm²): 385

 AVERAGE G.O. AREA (mm²): 0.013771

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (ft ³)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (grains/ft ³)	TOTAL ASBESTOS AIR CONC. (grains/ft ³)	TOTAL ASBESTOS FILTER CONC. (gr./mm ²)	AIR CONC. FOR STRICT. 0.558-5.0µm	AIR CONC. FOR STRICT. >5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-09-024-2184	North area on roof	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
02	T02-09-024-2185	South area on roof	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
03	T02-09-024-2186	Middle area on roof	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
04	T02-09-024-2187	Entrance to roof	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA
05	T02-09-024-2188	On stairway 6 th floor	1800	4	0.0551	0.0039	<0.0039	<18.15	NA	NA	NA	NA

 ANALYST
H. Simakri

 LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is replicated solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athena Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 922-8077
Fax (212) 922-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr + 1/2

12 hr.⁺/a 6 hr.⁺/a 3 hr.⁺/a Immediate⁺/a

P.O.

PAGE 2 OF 1

CLIENT: D & a

PROJECT: hoof cleaning

LOCATION: 101 Maiden Lane

W&P FILE #: 1079, 01, 02

LABORATORY:

ANALYSIS METHOD:			TEM

AMERICAN HERPETOLOGICAL SOCIETY
7400
circle one

TECHNICIAN: Ronald King

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE		TIME		TOTAL TIME	VOLUME (liters)	CONCENTR. (fib/cc.)
				START	STOP	ON	OFF			
01	North area on Roof	3		Y	Y	09:00	16:30	450	1800	
02	South area on Roof	3		Y	Y	09:02	16:32	450	1800	
03	Middle area on Roof	3		Y	Y	09:03	16:33	450	1800	
04	Entrance to Roof	3		Y	Y	09:06	16:36	450	1800	
05	On Stairway b th FL	3		Y	Y	09:15	16:45	450	1800	
06	Field blank			—	—	—	—	—	—	
07	Field blank			—	—	—	—	—	—	
08	Field blank			—	—	—	—	—	—	

COMMENTS.

T02-09-024

SAMPLE BY: Ronald King DATE: 9/1/01

SIGNATURE: Ronald King

RELEASED BY: Rona id kmr DATE: 9/7/02

SIGNATURE: David King

RECEIVED BY: A CATHAL DATE: 9/8/02

SIGNATURE: _____

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

Asbestos Inspection Report

Premise No. 101 MAIDEN LANE					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 68	Lot 10	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		

WEDNESDAY SEPTEMBER 4 2002

HANGING SCAFFOLD IS ERECTED IN PREPARATION FOR THE FACADE CLEAN UP ON THE EAST (PEARL STREET) FACE OF THE BUILDING. THE FACADES OF THE BUILDING CONTAINS SEVERAL AREAS OF CRACKED AND LOOSE BRICK. DURING THE ERECTION OF THE HANGING SCAFFOLD FOUR LOOSE BRICKS BECAME DISLODGED. NO INJURIES OCCURRED AS A RESULT OF THE FALLING BRICK.

FRIDAY SEPTEMBER 6 2002

THE CLEAN UP OF THE ROOF WORK AREA BEGINS AFTER THE INSTALLATION OF CRITICALS.

SATURDAY SEPTEMBER 7 2002

THE CLEAN UP OF THE EAST (PEARL STREET) FACADE AND ONE HALF OF THE SOUTH (MAIDEN LANE) FACADE WAS CONDUCTED TODAY. DUE TO SEVERAL AREAS OF LOOSE AND CRACKED BRICK NO POWER WASHING OF THE FACADE SURFACES OCCURRED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY LUIS SOTO (CERTIFICATE # AH 00 20894 EXP 03/03). CLEAN UP ACTIVITIES ON THE ROOF OCCURRED SIMULTANEOUSLY. AIR MONITORING FOR THAT PORTION OF THE CLEAN UP WAS PERFORMED BY RONALD KING (CERTIFICATE # AH 98-20226 EXP 10/02).

SUNDAY SEPTEMBER 8 2002

THE CLEAN UP OF THE SECOND HALF OF THE SOUTH (MAIDEN LANE) FACADE WAS CONDUCTED TODAY. THE CLEAN UP OF THE ROOF WAS COMPLETED TODAY. AIR MONITORING FOR THE FACADE CLEAN UP WAS PERFORMED BY LUIS SOTO. AIR MONITORING FOR THE ROOF CLEAN UP WAS PERFORMED BY

Asbestos Inspection Report

Premise No. 101 MAIDEN LANE	Inspection Date: AS NOTED
Inspector Dennis Antzoulatos	Page <u>2</u> of <u>2</u>
SUNDAY SEPTEMBER 8 2002 (CONTINUED) RONALD KING. A LARGE HOLE IN THE ROOF SURFACE (PRE-EXISTING) WAS PATCHED BY THE CONTRACTOR. "FINAL" AIR SAMPLING WAS PERFORMED FOR THE ROOF WORK AREA DUE TO EARLY STOPPAGE OF THE "DURING" AIR SAMPLING.	
MONDAY SEPTEMBER 9, 2002 THE CLEAN UP OF THE SET BACK ROOF AREA IS CONDUCTED TODAY. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP PROJECT IS PERFORMED BY FAYED ELGENDI (CERTIFICATE # AH 01 11631 EXP 03/03) OF WARREN & PANZER ENGINEERS. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES NO VISIBLE WTC DEBRIS WAS OBSERVED.	

09/11/2002 19:40 FAX 718 784 4085

010



ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490
Fax. (718) 784-4085

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.
 LABORATORY ID #: T02-09-032
 ANALYT. METHODOLOGY: AIHERA
 FILTER TYPE: M.C.E.
 AVERAGE G.O. AREA (mm²): 0.013771

PROJECT: NYC DEP, 101 Maiden Lane
 DATE OF REPORT: 09/10/02
 DATE OF ANALYSIS: 09/10/02
 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O. % ANAL YZED	AREA ANALY ZED (mm ²)	ANALYT. SENSITIVITY (Mnrd./cm ²)	TOTAL ASBESTOS AIR CONC. (struc./cm ²)	TOTAL ASBESTOS FILTER CONC. (str. Asst ²)	AIR CONC. FOR STRUCT. 0.55<5um	AIR CONC. FOR STRUCT. S25Mum	ASBEST. TYPE CHYRS.	ANALYT. ASBEST. TYPE SPECIFY
01	T02-09-032-2229	East Roof Top	1800	4	0.0551	0.0039	0.0039	18.15	0.0039	<0.0039	Chrys.	NA
02	T02-09-032-2230	West Roof Top	1800	4	0.0551	0.0039	0.0039	<18.15	NA	NA	NA	NA
03	T02-09-032-2231	North East Roof Top	1800	4	0.0551	0.0039	0.0039	18.15	<0.0039	0.0039	Chrys.	NA
04	T02-09-032-2232	North West Roof Top	1800	4	0.0551	0.0039	0.0039	<18.15	NA	NA	NA	NA
05	T02-09-032-2233	Adjacent Roof Top (Electric room)	1800	4	0.0551	0.0039	0.0039	<18.15	NA	NA	NA	NA

E. Siokri

ANALYST
E. Siokri

S. Dorigaris

LABORATORY DIRECTOR
Spiru Dorigaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES) is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc. did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used as claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

09/11/2002 19:40 FAX 718 784 4083

011

220 East 65th Street
New York, NY 10017
(212) 922-0877
Fax (212) 922-0830

WARREN & PANZER ENGINEERS, P.C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

CLIENT: NYC- DEP. PROJECT: ROOF CLEARING/DEMOLITION ANALYSIS METHOD: PCM TEM TEM LABORATORY: ATC- INC. CONTACT: Barry

LOCATION: 101 MAIDEN LANE, NYC, NY 10002 circle one AMERA EPA LEVEL N

TECHNICIAN: FAYED EL-GHEDDI

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
01	EAST ROOF TOP	3		3	0856 1856	600	1800	
02	WEST ROOF TOP	1		1	0857 1857	600	1800	
03	N.EAST ROOF TOP	1		1	0858 1858	600	1800	
04	N.WEST ROOF TOP	1		1	0859 1859	600	1800	
05	ADJ. EL. ROOF TOP (ELEC. RM)	3		3	0900 1900	600	1800	
06	FIELD BLANK	1		1				
07	FIELD BLANK	1		1				
08	FIELD BLANK	1		1				

COMMENTS: FAYED EL-GHEDDI
FAX # (212) 922-0830
THANK YOU.

SAMPLE BY: FAYED EL-GHEDDI	DATE: 9.9.02
SIGNATURE: F. El-Ghedi	
RELEASED BY: FAYED EL-GHEDDI	DATE: 9/9/02
SIGNATURE: F. El-Ghedi	
RECEIVED BY: [Signature]	DATE: 9/9/02
SIGNATURE: [Signature]	

SAMPLE TYPE CODES	
1 Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

09/11/2002 19:41 FAX 718 784 4085

012

**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7999
Fax. (718) 784-4085**AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-09-031

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013771

PROJECT: NYC DEP, 101 Maiden Lane

DATE OF REPORT: 09/09/02

DATE OF ANALYSIS: 09/09/02

EFFECTIVE FILTER AREA (mm²): 385**LABORATORY RESULTS**

CLIENT #	LAB. ID	LOCATION	VOLUME (L)	G.O. % ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (struct./cm ²)	TOTAL ASBESTOS FILTER CONC. (str./mm ²)	AIR CONC. FOR STRUCT. 0.553-5µm	AIR CONC. FOR STRUCT. 9.25-9µm	ASBEST. TYPE CHRYS.	ANALYT. ASBEST. TYPE SPECIFY
01	T02-09-031-2224	North area on roof	1440	4	0.0551	0.0049	<0.0049	<18.15	NA	NA	NA	NA
02	T02-09-031-2225	East area on roof	1440	4	0.0551	0.0049	<0.0049	<18.15	NA	NA	NA	NA
03	T02-09-031-2226	Middle area on roof	1440	4	0.0551	0.0049	<0.0049	<18.15	NA	NA	NA	NA
04	T02-09-031-2227	West area on roof	1440	4	0.0551	0.0049	0.0049	18.15	<0.0049	0.0049	NA	Actn.
05	T02-09-031-2228	South area on roof	1440	4	0.0551	0.0049	<0.0049	<18.15	NA	NA	NA	NA

ANALYST
R. DiMicheleLABORATORY DIRECTOR
Spina Dominguez

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Air sampling cassette will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported asbestos concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athena Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

Q.

התאחדות העובדים

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION