

WTC Visual Survey Form

Premise Address: <u>9-15 Murray St</u>			
Block:	Residential ☒ Commercial ☐	Name of Building:	
Lot:	Mix Use ☐ Other ☐		
# of Stories:	AKA's:		
Building Owner/Management:		Telephone Number: ()	
Name:		FAX: ()	
Address:			
On Site Contact:			
Name:		Telephone Number: ()	
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No		Locations: _____	
ACM Clean Up ☐ Yes ☐ No		Locations: _____	
Air Monitoring ☐ Yes ☐ No		Locations: _____	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Brick windows etc. The entire facade is cleaned</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ^{Light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 3/22/2002Inspection Team: Name: AL

Agency: _____

Name: _____ Agency: _____

ENTERED