

Page: 1 Document Name: Extra

```

02/05/02                N.Y.C. DEPARTMENT OF BUILDINGS                BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
41..... MURRAY STREET..... 1 MANHATTAN        10007 BIN# 1001445
DCP GEOGRAPHICAL INFORMATION:
MURRAY STREET          41 - 41                HEALTH AREA : 77        TAX BLK: 133..
MURRAY STREET          43 - 43                CENSUS TRACT: 1003     TAX LOT: 7501.
                                           COMMUNITY BD: 101     CONDO :
                                           MULTI STRUCT: 2      CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE:  DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : M. & A RESIDENCES INC           M & A RESIDENCES INC
CORP. NAME : C/O ANDREWS BUILDING CORP        LPC LANDMARK STATUS: CALENDARED
ADDRESS   : 666 BROADWAY                     DOB LOCAL LAW STATUS: YES
          NEW YORK NY 10012-2317
DOF BUILDING INFORMATION:                    TRANS LAND VALUE: 400,000
BLDG SIZE; ** UNKNOWN **                    TAX EXEMPT FLAG : NO
LOT SIZE: ** UNKNOWN **                    TAX EXEMPT CLASS:
BLDG CLASS : R9 CONDOMINIUMS                CITY OWNERSHIP : NO
STORIES   : 0                               UPDATE DATE : 01/12/02
FOR CITY  } MGMT TYPE:      MGMT CODE:      MGMT CODE NAME:
OWNERSHIP }                MGMT HOLDER CODE: MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN   PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```

Date: 2/5/ 2 Time: 12:45:11 PM

WTC Visual Survey Form

1084849

Premise Address: <u>43 MURRAY</u>		
Block: <u>133</u>	Residential ☐ Commercial ☐	Name of Building: <u>See 41 Murray</u>
Lot: <u>7301</u>	Mix Use ☐ Other ☐	
# of Stories: <u>6</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc. ASBESTOS DEBRIS</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ^{Light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: <u>INSPECTED FROM 53 MURRAY</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>ROAD CONSTRUCTION</u>					

Date: 01/27/2002Inspection Team: Name: AL
Name: HINRIKAgency: _____
Agency: _____