

ASBESTOS INSPECTION REPORT

REMISE NO.		STREET				INSPECTION DATE	
45 Murray		street				8/17/02	
LOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
Facade	10007	1	133	7		AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
ALPHONSO PLUMPTRE			TRU 1232 MW02				
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				SAMPLE NO.			
3010 BURNS AVE CITY WANTAGH							
STATE	ZIP	PHONE	SAMPLE NO.				
N.Y	11793	(616) 781-3000					
LABORATORY NAME				OWNERS NAME			
WARREN & PANZER ENGINEERS PC				LUI CHI CHEN			
ADDRESS		CITY		ADDRESS		CITY	
228 E. 45TH ST		N.Y		45 Murray St		N.Y	
STATE	ZIP	PHONE	STATE				
N.Y	10017	(212) 922-0077	N.Y ZIP 10007 PHONE				
CONTACT PERSON:				TIME OF INSPECTION FROM: 7:15 am/pm TO: 12:30 am/pm			
INSPECTION DISCLOSED:							

The Cleanup started at about 7:15 am and at about 8:10 am a tenant on the 2nd floor tried to pull down his apartment window which fell on him. Immediately we called the EMS and he refused treatment or go to the hospital. We continued the facade cleaning and was later inspected without any visible debris on it.

NOV #	INFRACTIONS	RESULT CODE
		5
NOV #		SUPERVISORS INITIALS
		RP

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 3093

FILE