

ASBESTOS INSPECTION REPORT

REMISE NO.		STREET				INSPECTION DATE	
47		Murray St				8/31/02	
LOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
2/F	10007	1	133	8	1	AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
ALPHONSO PLUMPTRE							
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				CITY			
3010 BURNS AVE				WANTAGH			
STATE		ZIP	PHONE		SAMPLE NO.		
N.Y.		11793	(516) 781-3000				
LABORATORY NAME				OWNERS NAME			
WARREN & PANZER ENGINEERS, PC				47 Murray Street ASSO Inc			
ADDRESS		CITY		ADDRESS		CITY	
228 E. 45TH ST		N.Y.		47 Murray St		N.Y.	
STATE		ZIP	PHONE		STATE		ZIP
N.Y.		10017	(212) 922-0077		N.Y.		10007
CONTACT PERSON:				TIME OF INSPECTION FROM: 7 AM/pm TO: 12 PM/pm			
INSPECTION DISCLOSED:							

The roof was cleaned on 8/27/02 and was later inspected and there was no visible debris observed.

The facade was cleaned on 8/21/02 and were thoroughly cleaned. No visible debris observed after the cleaning.

NOV #	#IN FRACTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						pl

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 309

FILE