

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 4420 0

Basis of Inspection:

TRU0921MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/21/02

PROJ. COMPLETION DATE: 7/25/02

I. FACILITY

ADDRESS: 51 MURRAY ST. BORO: MANHATTAN ZIP: 10007

TYPE OFFACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: 51 UNITED CORP.

Contact PAMELA LEE

TEL #:

ADDRESS: 51 MURRAY ST. CITY: NY STATE: NY ZIP: 10007

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: FIBER CONTROL INC.

TEL #: (516) 781-3000 FEDERAL EMPLOYER IDENTIFICATION #: PII

ADDRESS: 3010 BURNS AVE CITY: WANTAGH STATE: NY ZIP: 11793

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: SCIENTIFIC LABORATORIES INC - NEW YORK CI

NYS ELAP #: 11480

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☐ WEEKENDS ☐ WEEKDAYSINSPECTOR NAME: Alphonso Plunget SQUAD #: 1 BADGE #: A010DATE OF INSPECTION: 6/25/02 TIME OF INSPECTION: From: 11:15 AM ☒ PM ☐To: 6:00 AM ☐ PM ☒

Contact at site: PAMELA LEE

Inspection disclosed that the following sections were complied with: (Check all that apply)

☐ 1-51 - Notifications, Reports, Pla	☐ 1-71 - Air Sampling and Monitorin	☐ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☐ 1-116 - Work Place Preparation	☐ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☐ 1-137 - ACM Disturbance, RemoveL, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	

☐ Project not started

Inspection

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /☐ Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat☐ Follow up necessary on / /Samples taken: ☐ No ☐ Yes 1 2 34 5 6 Photos taken: ☐ Yes ☐ No

Additional comments:

The entire roof was cleaned and did
failed air test and the roof was recleaned and
washed. Another air test was done and passed
including the visual inspection. The facade
was cleaned and passed visual inspection on
7/13/02.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS