



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 23, 2002

51 United Corp.
51 Murray Street
New York, NY 10007-2233

**Subject: 51 MURRAY STREET
Second Notice**

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

A handwritten signature in black ink, appearing to read "R. Radhakrishnan".

R. Radhakrishnan, P.E.
Director
Asbestos Control Program



(718) DEP-HELP

WTC Visual Survey Form

Premise Address: 51 Murray

Block: **Residential** ☐ **Commercial** ☒ **Name of Building:**

Lot: **Mix Use** ☐ **Other** ☐

of Stories: 5 **AKA's:**

Building Owner/Management: **Telephone Number:** ()

Name: **FAX:** ()

Address:

On Site Contact: **Telephone Number:** ()

Name:

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No **Locations:**

ACM Clean Up ☐ Yes ☐ No **Locations:**

Air Monitoring ☐ Yes ☐ No **Locations:**

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: broken windows etc windows dirty

Roof

Debris: ☐ No Visible /Fine Layer ^{light dust} ☒ 1/2 to 1" 1 dust ☐ > 1" 1 dust.

Description: INSPECTED FROM 53 PARK PLACE

Setbacks N/A ☒

Floor:	Debris:
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments ROAD CONSTRUCTION

Date: 01/27/2002

Inspection Team: Name: AT
Name: HINICKY Agency: