

TOTAL FEET: 1950 0

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

Basis of Inspection:

TRU0920MNO2

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/21/02

PROJ. COMPLETION DATE: 6/29/02

I. FACILITY

ADDRESS: 49 MURRAY ST. BORO: MANHATTAN ZIP: 10007

TYPE OFFACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: 49 MURRAY HOUSES CONDOMINIUM

Contact

TEL #:

ADDRESS: 49 MURRAY ST. CITY: NY STATE: NY ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: FIBER CONTROL INC.

TEL #: (516) 781-3000 FEDERAL EMPLOYER IDENTIFICATION # PII

ADDRESS: 3010 BURNS AVE CITY: WANTAGH STATE: NY ZIP: 11793

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: SCIENTIFIC LABORATORIES INC - NEW YORK CI

NYS ELAP #: 11480

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☐ WEEKENDS ☐ WEEKDAYS

INSPECTOR NAME: Alfonso Plungetre SQUAD #: 1 BADGE #: 4010

DATE OF INSPECTION: 7/13/02 TIME OF INSPECTION: From: 2:30 AM ☐ PM ☒

To: 4:00 AM ☐ PM ☒

Contact at site:

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|---|--|---|
| ☐ 1-51 - Notifications, Reports, Pla | ☐ 1-71 - Air Sampling and Monitorin | ☐ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☐ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☐ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |

☐ Project not started

Inspection

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☐ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☐ No

Additional comments:

The cleanup of the facade is complete
and no visible debris observed after the cleanup.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS