

WTC Visual Survey Form

Premise Address: 110 Liberty St - Closed		
Block: 52	Residential ☐ Commercial ☐	Name of Building:
Lot: 7501	Mix Use ☐ Other ☐	
# of Stories: 3	AKA's: 113-117 Liberty St	
Building Owner/Management:		Telephone Number: ()
Name: NONE		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"					
Description: Inspected from roof of 125 Cedar St					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments Directly in front of WTC South					

Date: 1/25/2002

Inspection Team: Name: CAPR

Agency: DCP

Name: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>110 Liberty St - Closed</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>2</u>	AKA's:	
Building Owner/Management: <u>NONC</u>		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1"Description: Inspected from top roof of 100 TrinitySetbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25/2002
 Inspection Team: Name: CARL LUTCHMCO Agency: DEP
 Name: _____ Agency: _____

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
110..... LIBERTY STREET..... 1 MANHATTAN 10006 BIN# 1001042
DCP GEOGRAPHICAL INFORMATION:
LIBERTY STREET 110 - 114 HEALTH AREA : 77 TAX BLK: 52...
CEDAR STREET 113 - 117 CENSUS TRACT: 2001 TAX LOT: 7501.
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : BALDWIN REALTY, AGENT BALDWIN REALTY, AGENT
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 113 CEDAR ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10006-1061
DOF BUILDING INFORMATION: TRANS LAND VALUE: 801,513
BLDG SIZE; ** UNKNOWN ** TAX EXEMPT FLAG : NO
LOT SIZE: ** UNKNOWN ** TAX EXEMPT CLASS:
BLDG CLASS : R0 CONDOMINIUMS CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:07:12 PM

```

01/29/02                N.Y.C. DEPARTMENT OF BUILDINGS                BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
110..... LIBERTY STREET..... 1 MANHATTAN        10006 BIN# 1001042
DCP GEOGRAPHICAL INFORMATION:
LIBERTY STREET          110 - 114                HEALTH AREA : 77      TAX BLK: 52...
CEDAR STREET            113 - 117                CENSUS TRACT:  2001   TAX LOT: 7501.
                                           COMMUNITY BD: 101    CONDO   :
                                           MULTI STRUCT: 1      CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE:  DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : BALDWIN REALTY, AGENT            BALDWIN REALTY, AGENT
CORP. NAME :                                  LPC LANDMARK  STATUS: NO
ADDRESS    : 113          CEDAR ST             DOB LOCAL LAW STATUS: NO
                NEW YORK NY 10006-1061
DOF BUILDING INFORMATION:                      TRANS LAND VALUE: 801,513
BLDG SIZE; ** UNKNOWN **                      TAX EXEMPT FLAG : NO
LOT  SIZE: ** UNKNOWN **                      TAX EXEMPT CLASS:
BLDG CLASS : R0 CONDOMINIUMS                  CITY OWNERSHIP  : NO
STORIES    : 5                                UPDATE DATE     : 01/12/02
FOR CITY   } MGMT TYPE:      MGMT CODE:        MGMT CODE NAME:
OWNERSHIP  }                MGMT HOLDER CODE:  MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN   PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```