

**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT**

TOTAL FEET: 12678 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

TRU1103MN02

FL	SF	LF
roof	5,509	0
faça	7,169	0

**NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)**

FEE EXEMPT: Yes
1. \$0.00

START DATE: 7/16/02 COMPLETION DATE: 7/30/02

I. FACILITY

ADDRESS: 110 LIBERTY STREET/113-117 CEDER ST BORO: MANHATTAN ZIP: 10004

TYPE OFFACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: BALDWIN REALTY, C/O CHARLES GANLER

TEL. #:

ADDRESS: n/a n/a CITY: n/a STATE: n/a ZIP: n/a

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: **PII**

ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: NJ ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.

TEL. #: (212) 922-0077

ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammoohan SQUAD #: 1 BADGE #: A076

DATE OF INSPECTION: 7/18/02 TIME OF INSPECTION: From: 8 am AM PM

To: 6 pm AM PM

Contact at site: Sasa Simic, Supervisors / Louis Soto, Project Monitor

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|---|--|---|
| ☐ 1-51 - Notifications, Reports, Pla | ☐ 1-71 - Air Sampling and Monitorin | ☐ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☐ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☐ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |

☐ Project not started Inspection

☐ revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☒ No ☐ Yes 1 2 3
4 5 6 Photos taken: ☐ Yes ☒ No

Additional comments: Handlers started to clean the roof.
Elevated roof completed.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND
RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS
4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE
2
SUPERVISOR INITIALS
ROP

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 12678 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

Basis of Inspection: TRU1103MN02

FEE EXEMPT: Yes

1. \$0.00

FL	SF	LF
roof	5,509	0
faça	7,169	0

START DATE: 7/16/02 COMPLETION DATE: 7/30/02

I. FACILITY

ADDRESS: 110 LIBERT STREET/113-117 CEDER ST BORO: MANHATTAN ZIP: 10004

TYPE OFFACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: BALDWIN REALTY, C/O CHARLES GANLER

TEL. #:

ADDRESS: n/a n/a CITY: n/a STATE: n/a ZIP: n/a

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII

ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: NJ ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.

TEL. #: (212) 922-0077

ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammohan SQUAD #: 1 BADGE #: A078

DATE OF INSPECTION: 7/19/02 TIME OF INSPECTION: From: 8am AM PM

To: 5pm AM PM

Contact at site: Sasa Simic, Louis Soto

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|---|--|---|
| ☐ 1-51 - Notifications, Reports, Pla | ☐ 1-71 - Air Sampling and Monitorin | ☐ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☐ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☐ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |
| ☐ Project not started | | Inspection |

revealed all ACM to be intact. New start date: / /

☒ Project ongoing, expected completion date: / /☐ Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat☐ Follow up necessary on / /Samples taken: ☒ No Yes 1 2 34 5 6 Photos taken: Yes ☒ No

Additional comments: Lower setback and court yard cleaning was ongoing.

4³⁰pm. Court yard Completed and visual inspection revealed that the roof was clean.
Facade cleaning scheduled for tomorrow.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

2

SUPERVISOR INITIALS

PRP

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT

TOTAL FEET: 12678 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

TRU1103MN02

FEE EXEMPT: Yes

1. \$0.00

FL	SF	LF
roof	5,509	0
faça	7,169	0

START DATE: 7/16/02 COMPLETION DATE: 7/30/02

I. FACILITY

ADDRESS: 110 LIBERT STREET/113-117 CEDER ST BORO: MANHATTAN ZIP: 10004

TYPE OFFACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: BALDWIN REALTY, C/O CHARLES GANLER

TEL. #:

ADDRESS: n/a n/a CITY: n/a STATE: n/a ZIP: n/a

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII

ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: JN ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.

TEL. #: (212) 922-0077

ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Ramnathan SQUAD #: 1 BADGE #: A078

DATE OF INSPECTION: 7/20/02 TIME OF INSPECTION: From: 8am AM PM

To: 5pm AM PM

Contact at site: Sara Simic, Dipo Glemo.

Inspection disclosed that the following sections were complied with: (Check all that apply)

☐ 1-51 - Notifications, Reports, Pla	☐ 1-71 - Air Sampling and Monitorin	☐ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☐ 1-116 - Work Place Preparation	☐ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☐ 1-137 - ACM Disturbance, RemoveL, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	

Project not started

Inspection

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: ☒ No ☐ Yes 1 2 3

4 5 6 Photos taken: Yes ☒ No

Additional comments: Liberty street side below sidewalk bridge facade cleaning was completed at 8:45 am.

Liberty side facade washing started using boom truck. Visual inspection was conducted at 4:30 pm and was cleared.

Cedar street side facade was scheduled for 7/21/02.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

2

SUPERVISOR INITIALS

EP

**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT**

TOTAL FEET: 12678 0

TRU1103MN02

FL	SF	LF
roof	5,509	0
faça	7,169	0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

**NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)**

FEE EXEMPT: Yes
1. \$0.00

START DATE: 7/16/02 COMPLETION DATE: 7/30/02

I. FACILITY

ADDRESS: 110 LIBERT STREET/113-117 CEDER ST BORO: MANHATTAN ZIP: 10004
TYPE OFFACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: BALDWIN REALTY, C/O CHARLES GANLER

TEL. #:

ADDRESS: n/a n/a CITY: n/a STATE: n/a ZIP: n/a

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORPORATION

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII

ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: JN ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.

TEL. #: (212) 922-0077

ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammohan SQUAD #: 1 BADGE #: 1078

DATE OF INSPECTION: 7/21/02 TIME OF INSPECTION: From: 8 am AM PM

To: 6 pm AM PM

Contact at site: Sara Simic / Dipo Slemo

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|---|--|---|
| ☐ 1-51 - Notifications, Reports, Pla | ☐ 1-71 - Air Sampling and Monitorin | ☐ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☐ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☐ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |

☐ Project not started

☐ revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☒ Project completed on or about 7/21/02 All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☒ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☒ No

Additional comments: Crew started cleaning the cedert street side facade using boom truck. Visual inspection revealed that additional cleaning required and re cleaning was done. The clean-up was completed at 6 pm.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS

REP.