

WTC Visual Survey Form

Premise Address: 112 Liberty St - Closed

Block: Residential ☐ Commercial ☒ **Name of Building:**

Lot: Mix Use ☐ Other ☐

of Stories: 2 **AKA's:**

Building Owner/Management: NOW **Telephone Number:** ()

Name: **FAX:** ()

Address:

On Site Contact:

Name: **Telephone Number:** ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No **Locations:** _____

ACM Clean Up ☐ Yes ☐ No **Locations:** _____

Air Monitoring ☐ Yes ☐ No **Locations:** _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

North ☐ N/A

South ☐ N/A

East ☐ N/A

West ☐ N/A

Inspected

☒ Yes ☐ No

☐ Yes ☐ No

☐ Yes ☐ No

☐ Yes ☐ No

Debris

☐ No Visible/Fine Layer

☐ No Visible/Fine Layer

☐ No Visible/Fine Layer

☐ No Visible/Fine Layer

☐ ½ to 1"

☐ ½ to 1"

☐ ½ to 1"

☐ ½ to 1"

☒ > 1"

☐ > 1"

☐ > 1"

☐ > 1"

Facade Description:

Roof

Debris: ☐ No Visible /Fine Layer

☒ ½ to 1"

☐ > 1"

Description:

Inspected from roof of 100 Trinity Pl

Setbacks N/A ☐

Floor: _____

Floor: _____

Floor: _____

Floor: _____

Floor: _____

Debris: ☐ No Visible/Fine Layer

Debris: ☐ No Visible/Fine Layer

Debris: ☐ No Visible/Fine Layer

Debris: ☐ No Visible/Fine Layer

Debris: ☐ No Visible/Fine Layer

☐ ½ to 1"

☐ ½ to 1"

☐ ½ to 1"

☐ ½ to 1"

☐ ½ to 1"

☐ > 1"

☐ > 1"

☐ > 1"

☐ > 1"

☐ > 1"

Comments

Date: 1/15/2002

Inspection Team: Name: CARL LUTCHMAN

Agency: DCP

WTC Visual Survey Form

Premise Address: 112 Liberty St - Closed		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 2	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: NOWA		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"

Description: Inspected from roof of 100 Trinity Pl

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/15/2002

Inspection Team: Name: CARL LUTCHMAN

Agency: DCP

WTC Visual Survey Form

Premise Address: 113 Cedar St - Closed

Block: Residential ☐ Commercial ☐ **Name of Building:**

Lot: Mix Use ☐ Other ☐

of Stories: AKA's: 112 Liberty St

Building Owner/Management: None Telephone Number: ()

Name: FAX: ()

Address:

On Site Contact: Telephone Number: ()

Name:

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Ledges very dirty

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"

Description: Inspected from roof of 100 Trinity Pl

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/12/2002

Inspection Team: Name: Carl Lutz

Agency: DCR