

1079013 NOT FOUND

SAME BLOCK & LOT
AND BIN AS
110 LIBERTY.

WTC Visual Survey Form

1001042
1079013

Premise Address: <u>113 Cedar St - Closed</u>		
Block: <u>52</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>7501</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>113-117 Cedar St / 110-114 Liberty</u>	
Building Owner/Management Name: <u>None</u>		Telephone Number: ()
		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Ledges very dirty

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"Description: Inspected from roof of 100 Trinity PlSetbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25/2002Inspection Team: Name: Carol Lutz Agency: DCR

Name: _____ Agency: _____

Date: 2/5/ 2 Time: 12:34:37 PM